

[Next Unread Message](#)[View Message](#)

Sent on 04 23 2015 Expires on 05 02 2015
From Motorcycle Communications and Training
Subject SERVICE BULLETIN NOTICE: 2014-2015 CBR1000S (CBR1000RR SP) Rear Sho



Communications and Training

April 23, 2015

**SAFETY RECALL SERVICE BULLETIN NOTICE: 2014-2015 CBR1000S (CBR1000RR SP)
Rear Shock Absorber Repair**

Dear Honda Powersports Dealer:

Honda is posting the Service Bulletin in support of the SAFETY RECALL on 2014-2015 CBR1000S (CBR1000RR Special Edition) motorcycles for a potentially defective rear shock absorber assembly.

To search for applicable recalls on a specific unit, use *Unit Information on iN*.
To manage your affected inventory, use *eResponsibility Report*.

SERVICE BULLETIN

2014-2015 CBR1000S (CBR1000RR SP) REAR SHOCK ABSORBER REPAIR, which includes the affected VIN range, repair procedure, parts information, as well as warranty claim information, has been posted to *iN*.

AHM will provide dealers with a special strut to support the motorcycle in the shop while the shock is being repaired. This support strut will be automatically shipped to your dealership on Thursday April 23, 2015.

The strut will be shipped with a highlighted label stating:

ATTENTION

SERVICE MANAGER

ESSENTIAL SERVICE

TOOL ENCLOSED

The tool will be marked CBR1000S SB #1

CUSTOMER NOTIFICATION

AHM intends to mail customer letters as early as May 8, 2015 based on vehicle registration information.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine at 1-800-421-1900, Option 9, or through TechLine Connect on *iN*, or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.

William Hanson

Manager

Communications and Training

Motorcycle Division

Bulletin Number: 15-0108

[!\[\]\(3dfb8d66e81160ad61421a3452093d1b_img.jpg\) **BACK TO TOP**](#)

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.