



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 7, 2015

Mr. Scott Callander
Triumph Motorcycles America, LTD
385 Walt Sanders Memorial Drive
Newnan, GA 30265

NVS-215KS
15V-255

Subject: Shock Absorber Damping Rod Nut may Loosen/Detach

Dear Mr. Callander:

This letter serves to acknowledge Triumph Motorcycles America, LTD's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TRIUMPH/DAYTONA 675 R/2014-2015
TRIUMPH/SPEED TRIPLE R/2014-2015

Mfr's Report Date: April 29, 2015

NHTSA Campaign Number: 15V-255

Components:

SUSPENSION:REAR

Potential Number of Units Affected: 566

Problem Description:

Triumph Motorcycles America, LTD (Triumph) is recalling certain model year 2014-2015 Daytona 675 R and Speed Triple R motorcycles manufactured January 1, 2014, to April 1, 2015. The affected motorcycles may have been built with an improperly manufactured rear shock absorber. The nut on the damper rod for these shock absorbers may loosen, resulting in a loss of damping and the possible disassembling of the shock.

Consequence:

If the piston rod nut loosens, shock absorber performance would be affected, possibly causing a loss of vehicle control and increasing the risk of a crash.

Remedy:

Triumph will notify owners, and dealers will replace the rear shock absorber, free of charge. The recall is expected to begin May 13, 2015. Owners may contact Triumph customer service at 1-678-854-2010. Triumph's number for this recall is SB524.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Triumph's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement