



YAMAHA MOTOR CORPORATION, U.S.A. 6555 Katella Avenue, Cypress, CA 90630-5101 800-962-7926

IMPORTANT SAFETY RECALL NOTICE

THIS NOTICE APPLIES TO YOUR VEHICLE, VIN

April 29, 2015

Campaign Code: 990095

Dear Yamaha Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Yamaha Motor Corporation, U.S.A. has decided that a defect which relates to motor vehicle safety exists in certain 2015-model YZFR1MF/FC ("YZF-R1M") motorcycles. Our records indicate that you own the affected motorcycle shown above.

The reason for this recall: In affected motorcycles, the rear shock absorber may not have been manufactured correctly; the piston rod nut may have been tightened before the piston had the correct full metal-to-metal contact. If so, it is possible for the nut to loosen, preventing proper rear suspension action, causing poor handling that could result in a crash with injury or death.

What Yamaha and your dealer will do: To correct this defect, your authorized Yamaha dealer will inspect a lot number on the shock absorber to see if it is affected. If it is, your dealer will replace the shock absorber with a new one that was manufactured correctly. The inspection takes about 0.3 hour time to do but be aware that your Yamaha dealer may need to keep your motorcycle for longer depending upon their current service schedule. If the shock absorber must be replaced, the procedure takes about 1.2 hours time to do once your dealer has the new shock absorber in stock. **There will be no charge to you for this procedure.**

What you should do now: Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your motorcycle for this service. Remember to take this letter with you when you take in your motorcycle.

You should not ride your affected motorcycle shown above until this modification is performed.

If you are unable to return to the Yamaha dealer who sold you the motorcycle, this service will be performed by any authorized Yamaha motorcycle dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the Yamaha web site at www.yamaha-motor.com.

If you have had this repair performed before you received this letter, you may be entitled to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this repair. For more information, contact Yamaha Customer Relations at 1-800-962-7926.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need help: If, after contacting your dealership, you have questions or concerns which the dealership is unable to answer, please write to:
Yamaha Motor Corporation, U.S.A.
Customer Relations Department
P.O. Box 6555
Cypress, CA 90630
Or call: 1-800-962-7926

If, after contacting Yamaha Customer Relations, you are still not satisfied that we have done our best to remedy the situation without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>. Refer to campaign 15V221.

If you no longer own this Yamaha: If you have sold your motorcycle to another party, please call us toll-free at 1-800-962-7926 with the name and address of the new owner, along with the serial number shown to the right of your name on the address label above.

We're sorry to cause you any inconvenience, but we are sincerely concerned about your safety and continued satisfaction with our products. Thank you for giving your attention to this important matter.

Sincerely,
Customer Support Group
Yamaha Motor Corporation, U.S.A.