



HYUNDAI | NEW THINKING.
NEW POSSIBILITIES.

Technical Service Bulletin

GROUP CAMPAIGN	NUMBER 15-01-025
DATE MAY 2015	MODEL(S) ACCENT (RB)

SUBJECT: OCCUPANT DETECTION SYSTEM (ODS) UPDATE
(RECALL CAMPAIGN 129)

GDS ECU Update

★ IMPORTANT

*** Dealer Stock and Retail Vehicles***

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must also perform all open recalls on used vehicles, demo and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the service department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.

Description:

This bulletin provides information related to the Occupant Detection System (ODS) update for certain 2015MY Accent vehicles. In ambient temperatures below zero degrees Fahrenheit, the system may not deactivate the front passenger air bag when an infant child restraint seat occupies the front passenger seat. This could result in injury from the front passenger airbag in the event of a crash.

Applicable Vehicles:

- Certain 2015 MY ACCENT (RB)

GDS INFORMATION:

EVENT #	DESCRIPTION
370	"370. RB PODS CONTROL LOGIC IMPROVEMENT"

NOTICE

This update is only available using the PC GDS. Refer to the General Instructions found in TSB: **15-GI-002** (PC GDS).

- You must initially perform GDS PODs-F Update in Auto Mode.
- If ECU update starts but then fails in Auto Mode, perform update in the Manual Mode to recover.

Warranty Information:

Model	Op Code	Operation	Op Time
ACCENT (RB)	51C025R0	PODS UPGRADE	0.3 M/H

NOTE: Use the applicable ODS P/N listed in the ROM ID Information Table from the following pages.

Verify the ECU ROM ID before updating the software.

ECU ROM ID TABLE:

MODEL	SYSTEM	PODS/PN	ROM ID	
			Currently in Vehicle	Latest
RB	PODs-F	88952-1R600	2443FF 2443AA	2443CC

MANUAL MODE PASSWORD INFORMATION:

MENU	PASSWORD
370.RB PODS CONTROL LOGIC IMPROVEMENT	1600