

Exhibit A1

Units with the following serial numbers have both defects A and B.

- 35Z12011401 to 35Z12090504
- 36Z12090701 to 36Z14050113

The serial number is located on the inside back wall of the APU (remove the cover) or on the outside of the unit, above the condenser fan.



Photographs of the defective parts are shown below as a reference.



Without Gusset (Defective)



With Gusset (Not Defective)

Defect A



Defect B

Additional Information:

- If you have not received your upgrade kits within 1 week of receiving this letter, please order through the dealer portal or contact Jodi Hirsch at jhirsch@idlefreesystems.com to order kit # 91705. The kits will include all required parts and installation instructions.
- Please provide the names and addresses of all owner/operators to whom you sold any of the APUs listed on attached Exhibits A1 and B1. If you have information indicating that any of these owners/operators sold the vehicle on which the defective APU was installed, please provide the names and addresses of the owners/operators to whom the vehicle was sold. Please provide this information to Jodi Hirsch at jhirsch@idlefreesystems.com.
- For additional information regarding BA600 (installation instructions, warranty, reimbursement information or standard labor hours), please refer to the dealer portal at idlefreetechnology.com. A login is required. Contact Pat Fleishauer at pfleishauer@idlefreesystems.com if you do not have a dealer login.