



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Telephone: 714-372-6000
www.mitsubishicars.com

Date: 5/28/2015

**To: All Mitsubishi Dealers
All Mitsubishi Dealership Service & Parts Managers**

Subject: Takata Air Bag Inflators

Pursuant to a Defect Information Report that TK Holdings Inc. (Takata) submitted to the National Highway Traffic Safety Administration (NHTSA), Safety Recall SR-14-012 – Lancer Front Passenger Air Bag Inflator will now be expanded to:

- Include all remaining 2005 Lancer/Lancer Sportback/Lancer Evolution vehicles and those 2006 Lancer/Lancer Evolution vehicles utilizing the inflator at issue
- Cover all affected vehicles nationwide, regardless of garaging or registration history

The original regional campaign covered certain 2004 – 2005 Lancer/Lancer Sportback/Lancer Evolution vehicles originally sold in, or ever registered in Florida, Georgia, Alabama, Mississippi, Louisiana, Texas, South Carolina, Puerto Rico, Hawaii, U.S. Virgin Islands, Guam, Saipan, and America Samoa.

These timely actions are being taken to demonstrate our “customer first” philosophy and we encourage you and your staff to demonstrate this philosophy when affected owners visit your dealership to have this important campaign completed.

Customer notification letters are scheduled to be sent in mid-June and you will soon be receiving an update to Safety Recall Bulletin SR-14-012.

In the interim, if you receive an inquiry regarding this recall, from a customer with a vehicle within the model/model year range, please check the Vehicle Superscreen to see if this recall is applicable and incomplete – the recall applicability has been update on all VINs affected by this expansion. If the recall needs to be completed, please follow the repair procedure outlined in SR-14-012.

Please continue to prioritize the completion of the existing campaigns in your shop scheduling.

Sincerely,

MMNA Fixed Operations