



Innovation that excites

NISSAN BULLETIN

2004-06 Sentra, 2004 Pathfinder National Takata Passenger Air Bag Inflator – VIN Expansion Voluntary Safety Recall Campaign

Reference: PM558, PM559, & R1508

Date: May 28, 2015

Attention: Dealer Principal, Sales, Service & Parts Managers

***** Dealer Announcement *****

Last week, NHTSA announced it had received four defect notification reports from Takata concerning their air bag inflators. Three of the four defect reports **do not** involve Nissan vehicles. The fourth report involves SPI inflators that are the subject of this announcement.

Nissan is recalling MY04-06 Sentra and MY04 Pathfinder vehicles throughout the United States to replace Takata SPI passenger air bag inflators. This recall expansion is intended to address vehicles equipped with SPI inflators that are not already subject to previously announced recalls. More specifically, this includes vehicles located both **inside** and **outside** the high humidity areas that were manufactured between early 2004 and EOP.

Campaign	Model	Model Years	Population Total	Production Range
PM558	Sentra (humid areas)	MY 2004-2006	~49,000	1/7/04 – 8/26/06
PM559	Sentra (non-humid areas)	MY 2004-2006	250,967	
R1508	Pathfinder	MY 2004	12,725	1/6/04 – 7/19/04

***** What Dealers Should Do *****

1. Verify if vehicles currently in dealer inventory or entering the dealer for service are affected by this recall campaign using the following Service Comm I.D.
 - **PM558** or **PM559** – Sentra
 - **R1508** - Pathfinder
2. Repair any vehicles using NTB13-062 or NTB14-080.

*****Repair Instructions*****

Dealers should continue to use the repair processes in campaign bulletin **NTB13-062 and NTB14-080** to perform this voluntary safety recall campaign. These bulletins will be updated to include the new campaign IDs and claims information and be visible on ASIST by the week of June 8th.

***** Parts and Claims Information *****

Part Number	Description
98561-4Z60A	Sentra Inflator
KH5FA-7993D	Pathfinder Inflator

NOTE: Parts are not restricted and may be ordered freely through normal process as needed. Rental should be provided only when inflator parts are not in stock.

Pathfinder:

Campaign ID	Description	Op Code	FRT
R1508	Remove & Replace Airbag Inflator	R15082	0.9 hrs.

Sentra:

Campaign ID	Description	Op Code	FRT
PM558	Remove & Replace Airbag Inflator	PM5580	0.7 hrs.
PM559		PM5590	0.7 hrs.
PM558	Inspect Airbag Inflator	PM5581	0.4 hrs.
PM559		PM5591	0.4 hrs.

Pathfinder & Sentra Expense Coding:

EXPENSE CODE	DESCRIPTION	AMOUNT	MAX TOTAL	APPLICABLE PNC
502	Rental Expense	\$40/Day	\$80	PM558, PM559 or R1508
041	Shorting Pin	\$0.50	\$0.50	

*******Vehicle Identification*******

There are approximately **299,967** MY2004-06 Sentra and **12,725** MY2004 Pathfinder vehicles affected by this voluntary safety recall. Vehicles subject to this action can be identified through:

- **SERVICE COMM** – Beginning May 28th, 2015 service departments can complete an inquiry in SERVICE COMM – **I.D. PM558, PM559, or R1508** – to determine if a vehicle is subject to this voluntary safety recall.

******* Dealer Responsibility *******

It is the dealer's responsibility to check Service Comm using the appropriate Campaign I.D. for the campaign status on each vehicle falling within the range of this voluntary safety recall campaign which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in dealer inventory. If a VIN subject to this recall campaign was part of a dealer trade, the letter associated with that VIN should be forwarded to the appropriate dealer for service completion.

******* Owner Notification *******

Nissan plans to begin notifying owners of potentially affected vehicles in June 2015 via U.S. Mail.

******* Questions & Answers *******

A consolidated Q&A document for all the Takata airbag inflator campaigns is available on www.NNAnet.com under my documents in the following categories:

- Parts>Campaigns>
- Sales>Campaigns>
- Service>Campaigns>

Hint search on keywords:

- R1302, R1407, PM358, PM458, PM559, R1508 (National recalls)
- P4236, PM459, PM558 (Regional recalls)