

GM CUSTOMER CARE AND AFTERSALES
DCS3670
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 3, 2015

Subject: 15352 - Safety Recall – Stop Delivery Until Completion of Recall
Brake Pedal Push Rod Retention Failure

Models: 2015 Cadillac ATS, CTS

To: All Cadillac Dealers

Attention: Dealer, Dealer Principal, General Manager, General Sales
Manager, New Vehicle Sales Manager, Parts and Service Director,
Parts Manager, Service Manager and Warranty Administrator

General Motors is releasing Safety Recall 15352 today. The total number of U.S. vehicles involved is approximately 2,163. Please see the attached bulletin for details.

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

Customer Letter Mailing

The customer letter mailing date has not yet been determined.

Global Connect (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated June 4, 2015. A list of involved vehicles in dealer inventory is attached to this message.

Campaign Initiation Detail Report (CIDR)

The CIDR will be available in the near future.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES