

[Next Unread Message](#)**View Message**

Sent on 06 05 2015 **Expires on** 09 02 2015
From Campaign Administration, Acura Parts, Service & Technical Division
Subject Airbag Recall Service Bulletin Posting Error

DATE: June 5, 2015

TO: All Acura Sales, Service & Parts Managers and Personnel
FROM: Campaign Administration, Acura Parts, Service & Technical Division
RE: Airbag Recall Service Bulletin Posting Error

Acura recently indicated that the expanded driver's airbag campaign was expected to launch on Friday, June 5, 2015. Due to unexpected systems-related delays, the launch of the campaign and related VIN inquiry population has been pushed to Tuesday, June 9, 2015.

This morning several driver inflator campaign bulletins directed dealers to two new inflator campaign bulletins. Unfortunately the iN VIN status inquiry was not functional for the new campaigns.

We are working to restore the original bulletins to SIS until the iN VIN status inquiry for the new campaigns is updated.

Continue to use the following bulletins:

- B09-033 *Safety Recall: Driver's Airbag Inflator Can Be Over-Pressurized*
- B10-026 *Safety Recall: Replacement Driver's Airbag Inflator Can Be Over-Pressurized*
- B14-029 *Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity*