



Recall Campaign

NHTSA # 15V-235 TC#2015-174

Job Code 9902237

- RC024 Inspection of Axle Tag for Date .2 per Axle** LCI Inspection Step 1
- RC025 Inspection of Drum for Type .2 per Drum ** LCI Inspection Step 2
- RC026 Replacment of Hub as required .5 per Hub

Action Required

Inspect Axle Tag for manufacture date of 3/13,3/17,4/10,4/13,4/14, or 4/15
ONLY if Date on Axle Tag matches one of the dates listed, procede to Inspect for type of drums on axle
 Compare manufacture date and drum type to LCI chart to confirm if hub must be replaced
 Replace required hub/s following LCI Trailer Axle Hub Replacement Instrufcions provided.

Axle DOM	Drum Type	Must Replace Hub?
3/13, 3/17	Tru Ryde	Yes
3/13, 3/17	Axle Tek	No
3/13, 3/17	LCI	No
4/10, 4/13, 4/14, 4/15	Tru Ryde	No
4/10, 4/13, 4/14, 4/15	Axle Tek	Yes
4/10, 4/13, 4/14, 4/15	LCI	No

Affected Units

- | | | |
|----------------------|---------|---------------|
| 2016 Autumn Ridge TT | 289BHS | G2815067-5078 |
| | 346RESA | G2845061-5066 |
| | 286KBS | G2875051-5057 |
| | 329BHU | G28G5063-5071 |
| 2016 AR-ONE MAX | 30BHU | G28Z5051-5058 |

PARTS KIT

Order required parts kit from LCI according to LCI instructions provided

LCI CONACT INFORMATION
574-537-8900 OR WARRANTY@LCI1.COM

IMPORTANT: PLEASE NOTE SPECIAL LCI INSTRUCTIONS REAGRDNIG WHAT IS REQUIRED ON CLAIMS FOR PROCESSING

