



Innovation that excites

# NISSAN BULLETIN

## 2015 Murano ABS Actuator Voluntary Safety Recall Campaign Update #1 – Campaign Bulletin/Parts Status

Reference: PC375  
Date: June 15, 2015

Attention: Dealer Principal, Sales, Service & Parts Managers

**A STOP SALE CONDITION IS IN EFFECT.**

**\*\*\*\*\* Dealer Announcement \*\*\*\*\***

As a follow-up to our campaign announcement on June 5, 2015, Nissan would like to inform dealers that a campaign technical service bulletin is now available. A **STOP SALE** remains in effect for affected vehicles in dealer inventory.

Dealers will need to continue to submit the parts order form included with the original announcement to obtain parts if the inspection indicates parts replacement is necessary. Nissan began shipping parts on Friday, June 12<sup>th</sup> for order forms received.

**IMPORTANT: It is a violation of Federal law for dealers to sell or deliver vehicles in their inventory covered by this notification until the campaign repair is performed.**

**Note:** If a retailed vehicle affected by this campaign visits the dealer for service, the dealer should inform the customer about the recall campaign and perform the inspection procedure to determine if ABS Actuator replacement is necessary.

- Rental is available under the campaign for affected vehicles requiring repair and awaiting parts
- Rental must be claimed under Op Code PC3751

EXPENSE CODE	DESCRIPTION	AMOUNT
502	Rental Expense	\$40 (per day)

**\*\*\*\*\* Repair Instructions \*\*\*\*\***

Campaign Bulletin **NTB15-054** is now available. The interim inspection procedure will be removed from ASIST.

- NNAnet.com – This procedure can be found on NNAnet.com under My Documents in the following categories:
  - Sales>Campaigns>
  - Parts>Campaigns>
  - Service>Campaigns>
    - **Key Word: PC375**

**NISSAN NORTH AMERICA, INC.**  
Aftersales DIVISION