



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 10, 2015

Mr. Joshua Chard
Director, Corporate and Product Safety
Altec Industries Inc.
210 Inverness Center Drive
Birmingham, AL 35242

NVS-215SM
15V-398

Subject: Rotation Bearing Fasteners may Fail

Dear Mr. Chard:

This letter serves to acknowledge Altec Industries Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ALTEC/AH125/2013-2015
ALTEC/AH150/2013-2015
ALTEC/HL125/2013-2015

Mfr's Report Date: June 17, 2015

NHTSA Campaign Number: 15V-398

Components:

EQUIPMENT:MECHANICAL

Potential Number of Units Affected: 23

Problem Description:

Altec Industries Inc. (Altec) is recalling certain model year 2013-2015 Altec AH125, HL125 and AH150 aerial devices manufactured January 7, 2013, to January 2, 2015. In the affected vehicles, the rotation bearing fasteners may fail.

Consequence:

If the fasteners that attach the aerial device to the truck fail, the boom may unintentionally move, increasing the risk of personal injury or death to the aerial device user or those nearby.

Remedy:

Altec will notify owners and instruct users to complete their annual torque inspection. Any bolts that break during the inspection will be replaced, free of charge. The recall is expected to begin July 29, 2015. Owners may contact Altec customer service at 1-877-462-5832. Altec's number for this recall is CSN 620.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with the first name being the most prominent.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement