

GM CUSTOMER CARE AND AFTERSALES  
DCS3707  
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 8, 2015

Subject: 09226C – Safety Recall  
Fuel Odor or Spotting on Ground – Replace Fuel Pump Module  
Revised Part Information, Service Procedure, and Warranty  
Transaction Information Sections

Models: 2006 Chevrolet Cobalt, Pontiac Pursuit, and Saturn ION Originally  
Sold or Currently Registered in Arizona, Nevada; 2007 Chevrolet  
Cobalt, Pontiac G5, Saturn ION Originally Sold or Currently  
Registered in Arizona, California, Florida, Nevada, Texas

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

The Service Procedure section has been revised. If it is determined that the fuel pump module requires replacement, dealers are to also replace the fuel tank and fuel tank filler pipe or filler hose, if necessary. Please discard all copies of bulletin 09226B.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES