



---

07/21/2015

## **New Safety Recall Advanced Communication – R34072115**

FCA US LLC announced a safety recall on certain 2015 model year (DP) Ram Trucks (4500 and 5500 series).

Some of the above vehicles have front suspension upper control arms that may have been improperly welded during the manufacturing process. The weld connecting the bushing loop to the upper control arm could break under certain driving conditions. A broken upper control arm could cause a loss of vehicle stability and/or a crash without warning.

FCA will conduct a voluntary safety recall on all involved vehicles to replace both front suspension upper control arms.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations  
FCA US LLC