



07/21/2015

New Safety Recall Advanced Communication – R24072115

FCA US LLC announced a safety recall on certain 2015 model year (UF) Chrysler 200 vehicles.

Some of the above vehicles have a Power Distribution Center (PDC) 12-wire connector that contains terminals that may have been damaged during the manufacturing process. Damaged PDC connector terminal(s) could cause intermittent electrical connection(s) which may result in the engine stalling without warning and/or the transaxle defaulting to “Neutral.” Having the engine stall and/or the transaxle default into “Neutral” under certain driving conditions could cause a crash without warning.

NOTE: The above condition may also cause additional non-safety related issue such as:

- Air Conditioning (A/C) blows warm air.
- “AWD System Unavailable Needs Service” message.
- “Service Park Brake” message.
- Park brake warning light illuminated.
- No engine cranking.
- Engine cranks, but no engine start.

FCA will conduct a voluntary safety recall on all involved vehicles to replace the 12-wire connector on vehicles equipped with a 3.6L engine. Vehicles equipped with a 2.4L engine will have the transmission wiring harness, which contains the 12-wire connector, replaced.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC