
June 5, 2015

42306-01891 Version 12

Safety Recall: Driver's Airbag Inflator Can Be Over-Pressurized

This bulletin is replaced by S/B 15-033, *Safety Recall: Driver's Airbag Inflator Can Be Over-Pressurized*.

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.