

Federal Recall Information

13KWE

Supplier

Kenworth Truck Company

Description

Recall 13KWE – T270-T370 Seat Belt Anchor Reinforcement

Release Date

4/15/2013

Introduction

Kenworth Truck Company has decided that a defect which relates to motor vehicle safety exists in certain Kenworth model T270/T370 vehicles manufactured between January 31, 2013 and February 4, 2013. A total of 17 US chassis and 0 Canadian chassis are involved in this recall. The chassis list and a copy of the customer letter are attached. The DWC and SIR online systems indicate chassis involved in this recall with the designator of **“13KWE”**.

Situation

On certain T270 and T370 models as identified above, the floor pan reinforcement bracket for the outboard seat belt floor attachment on the driver’s seat was positioned incorrectly during assembly. This reinforcement is employed to secure the seat belt anchor to the floor of the cab. Incorrect positioning of the reinforcement may result in a failure of the seat belt anchor mounting.

Resolution

The remedy for this recall is to relocate the seat belt anchor bracket reinforcement to the correct position (see Procedure section below).

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

The SIR system will indicate chassis involved in this recall with the designator of "**13KWE**" in the campaign field.

Submit Quick Claim 13KWE.

For Field...	Enter...
Failure Location	002-011-025
Failure Type	465 – Wrong Location
Claim Type	C
Campaign Number	13KWE
Labor	SRT 002-XXX @ 2.5 hours
CCC Notes	Recall 13KWE - relocate the seat belt anchor bracket reinforcement to the correct position

Parts

Parts required for this repair are:

Quantity	Part Number	Description
3	K041-751ZN	¼" steel Huck
3	HWC02114	¼" Collar

Labor

Kenworth will pay 2.5 hours for this repair (SRT 002-XXX).

Procedure

Refer to the attached procedure.

Attachments

 [13KWE Chlist for ePortal](#)

 [Recall 13KWE Repair Procedure](#)

 [13KWE USCustLtr](#)