

13142D - Safety Recall - Loss of Battery Charge - Replace Generator Control Module - Revised

Updated Date: Sep 15, 2015 9:00 ET

GM CUSTOMER CARE AND AFTERSALES

DCS3768

URGENT - DISTRIBUTE IMMEDIATELY

Date: September 15, 2015

Subject: 13142D – Safety Recall

Loss of Battery Charge - Replace Generator Control Module

Revised Service Procedure

Models: 2012-13 Buick LaCrosse, Regal; 2013 Chevrolet Malibu Eco

Equipped with eAssist

To: All Buick and Chevrolet Dealers

Attention: Service Department, Parts Department

Step 4, 5, and 6 have been added to the service procedure. Please discard all copies of bulletin 13142C.