



1. Affected part – Power steering pump



## 2. Pump mechanism



- The Cartridge provides pressured oil to Steering gear. (①)
- Extra oil is released through the Spool valve. (②)
- Pump inner pressure should be the same pressure as the Relief valve designed pressure (③).