



Michael A. Berardi
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 28, 2015

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD Advance Notice - Safety Recall 15S25
Certain 2016 Model Year F-53 and F-59 Vehicles
Transmission Selector Lever Cable Bracket Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
F-53 Motorhome	2016	Detroit Chassis Plant	June 1, 2015 through August 11, 2015
F-59 Stripped Chassis			

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

In some of the affected vehicles, the transmission selector lever cable bracket was manufactured out of specification causing the transmission selector lever cable to be installed incorrectly. This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position. Unintended vehicle movement may increase the risk of an injury or crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any of the affected vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers early November 2015, when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

OWNER NOTIFICATION MAILING SCHEDULE

Owners of record will be notified via first-class mail after repair instructions and parts ordering information are provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael A. Berardi". The signature is fluid and cursive, with a prominent initial "M".

Michael A. Berardi