



ABOVE & BEYOND

NOTIFICATION OF SAFETY RECALL P072 (NHTSA# 15V-600): SECOND ROW SEAT MANUAL RECLINE FUNCTIONALITY

SERVICE BULLETIN

29-SEP-15

NO.: SRE15-17

SECTION: RECALL

MARKET: USA

Jaguar Land Rover North America, LLC has informed the National Highway Traffic Safety Administration (NHTSA) of its intent to perform a voluntary Safety Recall involving certain 2015 model year Land Rover Range Rover Sport and Range Rover vehicles imported into the United States market. Information relating to the proposed Recall will be posted on the NHTSA website.

United States Federal regulations require that retailers must be advised of this Recall notification within three working days after government notification.

United States Federal law requires retailers to complete any outstanding safety Recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a retailer could result in a civil penalty of up to \$7,000.00 per vehicle.

This Recall Service Bulletin serves as notification to all Land Rover retailers in the United States that any affected new vehicles may not be sold and delivered for customer use until the Recall repair is completed.

AFFECTED VEHICLES

A total of 856 select vehicles within the VIN ranges listed below are affected.

- Range Rover Sport (LW; L494) SALWR2VFXFA538466-SALWR2VF6FA539727
..... SALWR2VF5FA628110-SALWR2VF8FA628957
- Range Rover (LG; L405) SALGS2VF7FA239784-SALGS2VF3FA241015

See attached for a list of unsold (as of 29 September 2015) vehicles affected by this program.

DESCRIPTION OF DEFECT

A potential issue has been identified on 2015 model year Range Rover Sport (LW; L494) and Range Rover (LG; L405) vehicles fitted with the manual recline second row seat system where the second row seat backrest may not latch robustly in position.

EFFECT ON VEHICLE OPERATION

It is possible the visual indication of correct latch (the operating lever) condition is false and misleading and as such, especially in the center second row seated position, the seatbelt may not correctly restrain the occupant during a crash, which increases the risk of injury.

SERVICE PROGRAM / REWORK ACTION

Owners will be notified and instructed to take their vehicle to a Land Rover dealer who will inspect the second row seat mechanism. If required, the retailer will fit the correct specification components.

There will be no charge to owners for this action.

Further communication will be published once the necessary rework action required for affected vehicles is finalized.

OWNER NOTIFICATION

Mailing of owner notification letters will occur on or before 13 November 2015.

ACTION TO BE TAKEN

Check DDW to ensure that a vehicle is affected by this program (P072) prior to undertaking any rework action.

Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the rework action.

Sold vehicles will be subject to the standard Recall notification and Recall bulletin process detailing the action required for vehicles in the hands of owners.

Retailers are advised that the use of affected vehicles as Sales Demonstrator or Service Loaner vehicles may be considered a violation of Federal legislation. Jaguar Land Rover North America, LLC recommends against using affected vehicles for demonstrator or loaner purposes. Please consult your own legal counsel if you have questions in this regard.

Thank you for your cooperation in this matter. Jaguar Land Rover North America apologizes for any inconvenience this may cause.

**SAFETY RECALL P072: UNSOLD AFFECTED VEHICLES
(AS OF 29 SEPTEMBER 2015)**

Dealer Code and Name		Chassis #	Model Line	Model Year
0104 Land Rover Encino		FA240264	Range Rover	2015
0116 Land Rover Lake Bluff		FA628178	Range Rover Sport	2015
0132 Land Rover San Antonio		FA539039	Range Rover Sport	2015
0132 Land Rover San Antonio		FA539224	Range Rover Sport	2015
0132 Land Rover San Antonio		FA628712	Range Rover Sport	2015
0156 Land Rover Hunt Valley		FA239881	Range Rover	2015
0163 Land Rover Richmond		FA539617	Range Rover Sport	2015
0173 Land Rover Cary		FA240364	Range Rover	2015
0173 Land Rover Cary		FA240843	Range Rover	2015
0173 Land Rover Cary		FA240998	Range Rover	2015
0173 Land Rover Cary		FA538852	Range Rover Sport	2015
0188 Land Rover Solon		FA240510	Range Rover	2015
0189 Land Rover Dublin		FA240841	Range Rover	2015
0192 British Motor Car Distributors, Ltd.		FA628657	Range Rover Sport	2015
0209 Land Rover Hinsdale		FA240410	Range Rover	2015
0209 Land Rover Hinsdale		FA628299	Range Rover Sport	2015
0212 Land Rover Main Line		FA240054	Range Rover	2015
0225 Land Rover Northfield		FA628424	Range Rover Sport	2015
0226 Land Rover Buffalo		FA538756	Range Rover Sport	2015
0228 Land Rover Tampa		FA628791	Range Rover Sport	2015
0233 Land Rover Greensboro		FA628756	Range Rover Sport	2015
0234 Land Rover Austin		FA538798	Range Rover Sport	2015
0234 Land Rover Austin		FA538982	Range Rover Sport	2015
0234 Land Rover Austin		FA628514	Range Rover Sport	2015
0235 Land Rover Louisville		FA240313	Range Rover	2015
0249 Land Rover New Orleans		FA538837	Range Rover Sport	2015
0251 Land Rover Harrisburg		FA240537	Range Rover	2015
0251 Land Rover Harrisburg		FA538877	Range Rover Sport	2015
0252 Land Rover Las Vegas		FA538851	Range Rover Sport	2015
0252 Land Rover Las Vegas		FA628147	Range Rover Sport	2015
0255 Land Rover Hanover		FA538879	Range Rover Sport	2015
0255 Land Rover Hanover		FA539136	Range Rover Sport	2015
0261 Land Rover Redwood City		FA239827	Range Rover	2015
0262 Land Rover Flatirons		FA628724	Range Rover Sport	2015
0270 Land Rover Bedford		FA240012	Range Rover	2015
0270 Land Rover Bedford		FA240127	Range Rover	2015

Dealer Code and Name		Chassis #	Model Line	Model Year
0277 Land Rover Milford		FA628348	Range Rover Sport	2015
0287 Hornburg Land Rover Los Angeles		FA539041	Range Rover Sport	2015
0291 Land Rover Seattle		FA240065	Range Rover	2015
0291 Land Rover Seattle		FA240158	Range Rover	2015
0296 Land Rover Tysons Corner		FA239941	Range Rover	2015
0296 Land Rover Tysons Corner		FA240052	Range Rover	2015
0302 Land Rover Fox Valley		FA240380	Range Rover	2015
0305 Land Rover Baton Rouge		FA539233	Range Rover Sport	2015
0317 Land Rover Huntsville		FA539185	Range Rover Sport	2015
0318 Land Rover Norwood		FA240451	Range Rover	2015
0319 Land Rover Chantilly		FA628806	Range Rover Sport	2015
0320 Land Rover West Columbia		FA628277	Range Rover Sport	2015
0332 Royal Land Rover Tucson		FA538932	Range Rover Sport	2015
0340 Hornburg Land Rover Santa Monica		FA539531	Range Rover Sport	2015
0342 Land Rover Fort Lauderdale		FA538473	Range Rover Sport	2015
0342 Land Rover Fort Lauderdale		FA538761	Range Rover Sport	2015
0348 Land Rover Hilton Head		FA539141	Range Rover Sport	2015
0361 Land Rover Rochester		FA628447	Range Rover Sport	2015
0362 Land Rover Princeton		FA240228	Range Rover	2015
0369 Land Rover Edison		FA240413	Range Rover	2015
0369 Land Rover Edison		FA240465	Range Rover	2015
0369 Land Rover Edison		FA240961	Range Rover	2015
0383 Land Rover Reno		FA539171	Range Rover Sport	2015
0388 Land Rover Annapolis		FA240881	Range Rover	2015
0388 Land Rover Annapolis		FA538892	Range Rover Sport	2015
0390 Land Rover Roanoke		FA240232	Range Rover	2015
0390 Land Rover Roanoke		FA539143	Range Rover Sport	2015
0391 Land Rover Palm Beach		FA240230	Range Rover	2015
0391 Land Rover Palm Beach		FA240714	Range Rover	2015
0391 Land Rover Palm Beach		FA240848	Range Rover	2015
0393 Land Rover Columbia		FA539047	Range Rover Sport	2015
0394 Land Rover Honolulu		FA539178	Range Rover Sport	2015
0395 Land Rover Jacksonville		FA628747	Range Rover Sport	2015
0397 Land Rover Roaring Fork		FA538919	Range Rover Sport	2015
0397 Land Rover Roaring Fork		FA539246	Range Rover Sport	2015
0602 Land Rover Huntington		FA628796	Range Rover Sport	2015
0604 Land Rover Darien		FA240639	Range Rover	2015