

GM CUSTOMER CARE AND AFTERSALES

DCS3798

URGENT - DISTRIBUTE IMMEDIATELY

Date: October 7, 2015

Subject: 15299A – Safety Recall
Driver Side Rear Pillar Interior Fires
Revised Service Procedure and Customer letter added

Models: 2013-2016 Cadillac ATS Sedan

To: All Cadillac Dealers

Attention: Dealer, Dealer Principal, General Manager, General Sales Manager,
Service Manager, Parts and Service Director, New Vehicle Sales
Manager, Used Vehicle Sales Manager

Bulletin 15299 has been updated to add the customer letter and an owner's manual insert. Please discard all copies of 15299.

Customer Letter Mailing

The customer letter mailing will begin on October 16, 2015.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES