

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Update Recall 15V-205: OC3 seat occupancy mat
Date: Thursday, October 15, 2015 5:15:56 PM

Publish Date: October 15, 2015
From: Technical Service
Expiration Date: October 29, 2015

DCSnet Message
Urgent



Subject: **Update Recall 15V-205: OC3 seat occupancy mat**

Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians

Message Text:

BMW AG is conducting a Voluntary Safety Recall involving the front passenger seat occupancy detection mat sensor in certain Model Year 2005-2006 MINI Cooper and Cooper S models, Model Year 2005-2008 MINI Cooper Convertible and Cooper S Convertible models.

A final notification letter has been mailed out for MINI Recall 15V-205, informing customers that they can have their vehicle repaired at this time.

Attached you will find Service Information bulletin M65 02 15, Q&A, Final Owner Notification Letter and Legal Notice for further information. Please contact your field representatives if you have any questions.

Sincerely, Eugene Aton, Technical Service

Attachments:

- [M65_02_15_QA\[815b93a2\].pdf](#)
- [M650215_Final_Letter\[815b93a1\].pdf](#)
- [M650215_4\[815b93a0\].pdf](#)
- [Legal_Recall_Notice_15V-205\[815b939f\].pdf](#)
- [M65_02_15_QA\[815b93a2\].pdf](#)
- [M650215_Final_Letter\[815b93a1\].pdf](#)
- [M650215_4\[815b93a0\].pdf](#)
- [Legal_Recall_Notice_15V-205\[815b939f\].pdf](#)

Recipients: MINI Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel