

GM CUSTOMER CARE AND AFTERSALES
DCS3828
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 30, 2015

Subject: 15150A – F/CMVSS Noncompliance Recall
Front Seat Hooks Not Installed Into Underbody
Customer Letter Added

Models: 2015 Chevrolet Colorado
2015 GMC Canyon

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New or Used Vehicle Sales
Manager, and Warranty Administrator

Bulletin 15150 has been revised to include a copy of the customer letter. Please discard all copies of bulletin 15150.

GM CUSTOMER CARE AND AFTERSALES