



Aftersales Bulletin

Area **Service Information**
Subject Delivery Stop for Ghost
Group 72
Reference 10 28 2015 01
Published date October 28, 2015
Version 01
Department Service Operations
Recipients All Service Managers, Parts Managers, Aftersales Managers and Service Technicians of Rolls-Royce Motor Cars Dealers



NHTSA safety recall:

Please be reminded that it is a violation of Federal law for you to sell, lease or deliver any vehicle covered by this notification until the recall repair has been performed. This means that dealers may not legally deliver new motor cars to customers until they are fixed or use/sell replacement equipment/parts subject to a recall. Please note also that substantial civil penalties apply to violations of this law. Perform the procedure outlined in this service information bulletin on all affected vehicles prior to customer delivery.

1. Situation

A delivery stop has been implemented for one vehicle that has the incorrect thorax airbag fitted to both front seats causing a possible non-compliance with NHTSA regulations.

Rolls-Royce Motor Cars took immediate action on discovering this issue and have stopped deliveries of affected vehicles and has authorized the replacement of the affected thorax airbag modules.

The repairs must be completed on the following chassis number prior to delivery.

- UX53018

Procedure:

Please refer to Service Information Bulletin # 10 28 2015-02 (Thorax Airbag Module Replacement)

If you have any questions, please contact your Aftersales Area Manager (AAM).

Bill McHugh
National Aftersales Manager
Rolls-Royce Motor Cars NA

James Fisher
National Technical Support Manager
Rolls-Royce Motor Cars NA

Rolls-Royce Motor Cars

Rolls-Royce Motor Cars NA, LLC
Mailing Address: P.O. Box 1227, Westwood, NJ 07675-1227
Office Address: 300 Chestnut Ridge Road, Woodcliff Lake, NJ 07677-7731
Telephone (201) 307-4117 Fax (201) 594-3495
enquiries@rolls-roycemotorcars.com www.rolls-roycemotorcars.com
A BMW Group Company