



# IMPORTANT SAFETY RECALL

November 2015

This notice applies to your vehicle, **VIN:** \_\_\_\_\_.

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

*Previously, you were notified that your 2011-2012 model year Chevrolet Malibu was involved in GM recall 15031. This letter is to inform you that parts are now available to repair your vehicle.*

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2011-2012 model year Chevrolet Malibu vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

## IMPORTANT

- Your vehicle is involved in GM safety recall 15031.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

### Why is your vehicle being recalled?

The flexible steel cable that connects the safety belt to the vehicle at the outside of the front outboard seating positions can fatigue and separate over time as a result of occupant movement into the seat. In certain seating positions, the seat belt's flexible steel cable (or "tensioner cable") can be located in a forward position allowing the occupant to sit on top of it while entering the vehicle. This action can bend the steel cable at a severe angle over the seat side shield, which over time may cause the cable to fatigue and separate. In a crash, a fatigued cable could break, reducing the effectiveness of the vehicle's safety belts and increasing the risk of injury to the occupant.

### What will we do?

Your GM dealer will replace both of your vehicle's front outboard lap anchor mounting brackets to relocate the tensioner. The dealer will also inspect the flexible steel cable and, if necessary, replace both front safety belt tensioners. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately one hour and thirty five minutes.

### What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

**Did you already pay for this repair?**

Even though you may have already had repairs for this condition, you will still need to take your vehicle to your dealer for additional repairs. If you have paid for repairs for the recall condition, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by October 31, 2016, unless state law specifies a longer reimbursement period.

**Do you have questions?**

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
Guam	1-671-648-8450	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 15V269.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jeffrey M. Boyer  
Vice President  
Global Vehicle Safety

Enclosure  
GM Recall #15031

## General Motors Product Field Action Customer Reimbursement Request Form

**This section to be completed by customer (please print)**

Customer Name: \_\_\_\_\_

Street Address or P. O. Box Number: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_

Daytime Telephone Number (include Area Code): \_\_\_\_\_

Evening Telephone Number (include Area Code): \_\_\_\_\_

Date Request Form and Supporting Documentation Submitted to Dealer: \_\_\_\_\_

Vehicle Identification Number of Involved Vehicle: \_\_\_\_\_  
(17 Characters)

Mileage at Time of Repair: \_\_\_\_\_ Date of Repair: \_\_\_\_\_

Amount of Reimbursement Requested: \$ \_\_\_\_\_

**THE FOLLOWING DOCUMENTATION MUST ACCOMPANY THIS REQUEST FORM.**

Original or clear copy of all receipts, invoices and/or repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- Description of problem, the repair performed, date of repair and who performed the repair.
- The total cost of the repair expense that is being requested.
- Proof of payment for the repair in question and the date of payment.

My signature to this document attests that all attached documents are genuine and I request reimbursement for the expense I incurred for the repair covered by this letter.

Customer's Signature: \_\_\_\_\_

Submit this request form and the required documents to your GM dealer for processing. All reasonable and customary costs to correct the condition described in the letter that came with this form will be considered for reimbursement. If your request is approved, you will receive a check from your dealer. If your request is denied, you will receive a written explanation for the denial from your dealer. If your request is incomplete, your dealer will advise you what documentation is needed to complete the request and offer you the opportunity to resubmit the request when the missing documents are available. If you have any questions about this process or have waited 30 or more days for a response from your dealer, please contact the GM Customer Assistance Center at 1-800-204-0261.

**This section to be completed by dealer (please print)**

Bulletin No.: \_\_\_\_\_ Request Approved: \_\_\_\_\_ Date: \_\_\_\_\_ Amount: \$ \_\_\_\_\_

Request Denied: \_\_\_\_\_ Date: \_\_\_\_\_ Reviewed By: \_\_\_\_\_

Reason: \_\_\_\_\_

**If denied, please provide a copy of this form to the customer and retain original for your files**