

# BMW



## **IMPORTANT SAFETY RECALL CORRECTION**

**This notice applies to your vehicle, 15V 318XTEST**

**February 2016**

### **Recall Campaign No. 15V-318: Driver-Side Front Air Bag Module**

Dear BMW Owner / Lessee:

BMW previously sent you a notice in accordance with the National Traffic and Motor Vehicle Safety Act. At that time, BMW AG had determined that a defect, which relates to motor vehicle safety, exists in certain Model Year 2003 and 2004 X5 Sports Activity Vehicles. Our records had indicated that you were the owner of a potentially affected vehicle.

**Since that time we have determined that your vehicle is not affected by this recall, as your BMW X5 does not contain the recalled module. There is no known defect with your vehicle in relation to this safety recall.**

We sincerely apologize for any inconvenience our database error may have caused; however, be assured that BMW is concerned about your safety and security.

### **OTHER INFORMATION**

If you are no longer the vehicle owner/lessee, we request that you provide us with the name and address of the new owner/lessee using the enclosed postage-paid card so that we can contact the new owner/lessee regarding this recall correction. If you are a lessor of this vehicle, Federal Regulations require you to forward this notice to your lessee within ten days.

Should you need additional assistance, you may contact BMW Customer Relations and Services via Email at [CustomerRelations@bmwusa.com](mailto:CustomerRelations@bmwusa.com) or by calling 1-800-525-7417 from 9 AM to 9 PM Eastern Time, Monday through Friday.

BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.

BMW of North America, LLC

**Company**

BMW of North America, LLC

BMW Group Company

**Mailing Address**

PO Box 1227  
Westwood, NJ  
07675-1227

**Telephone**

(800) 525-7417

**Fax**

(201) 930-8362

**E-mail**

CustomerRelations@  
bmwusa.com

**Website**

bmwusa.com



0000108