

02/29/2016

Safety Recall Technical Advisory (R46)

In early February of 2016, FCA launched Safety Recall R46 – Front Suspension Track Bar Frame Bracket. This **recall does not include RAM Power Wagon models** (sales code ACP). All Power Wagon Models have a unique track bar bracket. The recall track bar reinforcement brackets will not fit these models and should not be installed.

Approximately 500 **RAM Power Wagon owners were inadvertently sent a recall notice** for Safety Recall R46. These vehicles are not involved in this recall and do not have a safety issue.

All RAM Power Wagon Vehicle Identification Numbers (VIN's) have been removed from Recall R46.

Should a customer arrive at your dealership with a RAM Power Wagon to have Recall R46 performed, please inform them that their truck is not involved in this recall and that **no repair is required**.

Please feel free to **share this Technical Advisory with the customer** and provide them with a copy of this advisory for their records.

Thank You
Customer Services Field Operations
FCA US LLC