



TMS Toyota Customer Services
Product Quality and Service Support, Quality Compliance
Published March 10, 2016
Approved By: Tom Trisdale

Toyota Motor Sales, USA, Inc.
19001 South Western Avenue
Torrance, CA 90501
(310) 468-4000

To: All Toyota Dealer
From: Product Support Division

****Technical Instructions Available on TIS****

Safety Recall E04 – For Areas of High Absolute Humidity - Remedy Update
Certain 2003-2008 Model Year Corolla and Corolla Matrix Vehicles
Certain 2003-2006 Model Year Tundra Vehicles
Certain 2002-2007 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module

An additional repair procedure to replace the airbag assembly is now available for Corolla Matrix vehicles on TIS.

[Refer to the Dealer Letter and/or Technical Instructions on TIS for additional information.](#)

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.