

<p>POLICE INTERCEPTOR—AIR BAG WARNING LAMP— DIAGNOSTIC TROUBLE CODES (DTCS) B0050:11 OR B0050:13</p>	<p align="center">TSB 13-5-25</p>
---	--

FORD:
2013 Taurus

ISSUE

Some 2013 Taurus Police Interceptor sedan vehicles may exhibit an illuminated air bag warning lamp with DTCs B0050:11 or B0050:13.

ACTION

Follow the Service Procedure Step to correct the condition.

SERVICE PROCEDURE

Replace the front safety seat belt buckle. Refer to Workshop Manual, Section 501-20.

PART NUMBER	PART NAME
DG1Z-5461203-BA	Seat Belt Buckle

OPERATION	DESCRIPTION	TIME
130525A	2013 Taurus Police Interceptor Sedan: Check DTCs Replace The Right Safety Belt Buckle	0.9 Hr.
130525B	2013 Taurus Police Interceptor Sedan: Check DTCs Replace The Left Safety Belt Buckle	0.8 Hr.
130525C	2013 Taurus Police Interceptor Sedan: Check DTCs Replace Both Safety Belt Buckles	1.3 Hrs.

DEALER CODING

BASIC PART NO.
5461203

CONDITION
CODE
28

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage. Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.