



**SB-10057014-3865**

File in Section: -

Bulletin No.: P11340

Date: October, 2014

# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Extended Brake Pedal Travel

**Models:** 2015 Cadillac ATS, CTS (VIN A), XTS  
Built Between and Including the VIN Breakpoints Below

Model	VIN From	VIN To
XTS	F9119594	F9121969
CTS-A	F0103380	F0108222
ATS	F0103387	F0108243

### Condition/Concern

Some customers may comment on a "Soft" or "Fade" feeling in the brake pedal, or extended travel. This may be the cause of contamination inside of the Electronic Brake Control Module (EBCM).

### Recommendation/Instructions

Replace the EBCM. Refer to the Electronic Brake Control Module Replacement in SI.

### Parts Information

For part numbers and usage, Electronic Brake Control Module Kit in Group 04.720 of the appropriate Parts Catalog.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2410370	Electronic Brake Control Module Replacement	Use Published Labor Operation Time