



**FRONT SUSPENSION TRACK BAR  
FRAME BRACKET**

---

**IMPORTANT SAFETY RECALL INFORMATION** R46 / NHTSA 15V-541

This notice applies to your vehicle (VIN: xxxxxxxxxxxxxxxxxxxx).

Dear: (Name)

FCA US LLC has decided that a defect, which relates to motor vehicle safety, exists in certain 2013 and 2014 model year 2500/3500 series RAM trucks and 3500 series RAM cab chassis trucks equipped with a three link front suspension.

Due to a recall mailing processing issue, **your RAM Power Wagon was inadvertently included in the recall notification mailing list** for Safety Recall R46.

You were mailed safety recall notices asking you to bring your truck in to your local dealer for a front suspension inspection and/or repair. We ask that you please disregard all previous letters you received regarding Safety Recall R46. **There is no action required on your part to maintain the safe operating condition of your truck.**

Your RAM Power Wagon is equipped with a unique front suspension track bar bracket. Because your front suspension track bar bracket is of a different design, **your truck does not have the recall issue and does not require this repair.**

If you have additional questions or concerns about this issue, please contact the FCA Recall Assistance Center at 1-800-853-1403. An FCA representative will be glad to answer any further questions you may have regarding this issue.

We apologize for any inconvenience this issue may have caused, but we are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Services / Field Operations  
FCA US LLC