



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



19645/070127/0204



R. FILE
330 TOWN CENTER DR
STE 500
DEARBORN, MI 48126-2796

May 2016

***** IMPORTANT SAFETY RECALL ***
(PROGRAMA DE SEGURIDAD IMPORTANTE)**

**Safety Recall Notice 15S21 / NHTSA Recall 15V-319
Aviso de Revisión de Seguridad 15S21**

2013 Mustang Shelby GT500
Your Vehicle Identification Number (VIN):

In July 2015, Ford Motor Company sent you a letter announcing Safety Recall 15S21 (Driver Airbag Inflator Replacement) on your vehicle, with the VIN shown above. This letter is to inform you that we are expecting the newly designed driver airbag module for your vehicle to become available in the fourth quarter of this year. Ford Motor Company will notify you when the part is available to schedule a repair date with your dealer.

What is the issue? In certain vehicles, the front driver side airbag inflator housing may rupture in a crash necessitating deployment of the driver side frontal airbag. An airbag inflator rupture could result in metal fragments striking the driver or other occupants resulting in serious injury or death.

What if you no longer own this vehicle? If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.
You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

Thank you for your attention to this important matter.

Ford Customer Service Division