

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: 15V-318 Driver Front Air Bag Module SI B65 11 15 (Final Repair Update)
Date: Friday, August 19, 2016 2:35:32 PM

Publish Date: August 19, 2016
From: Parts Logistics
Expiration Date: September 02, 2016

DCSnet Message
Reference



Subject: **15V-318 Driver Front Air Bag Module SI B65 11 15 (Final Repair Update)**

To: All BMW Parts and Service Managers

Re: 15V-318 Driver Front Air Bag Module SI B65 11 15 (Final Repair Update)

The first batch of Customer Letters for E46, E39 and E53 final repair were mailed out today. This mailing involves customer vehicles that are currently or were ever registered in High Absolute Humidity areas such as Alabama, California, Florida, Georgia, Guam, Hawaii, Louisiana, Mississippi, Puerto Rico, Samoa, Texas, US Virgin Islands, Saipan and South Carolina as per the NHTSA requirements.

With the limited supply of parts available, we will begin accepting email request for those customer VINs which contain the final repair defect code 00 32 39 02 00.

Please submit your email request to specialpartsrequest@bmwna.com including the following information:

Subject Line: 15V-318 SIB 65 11 15
Dealer Location Code:
Part Number:
VIN Number:

Orders will be placed on your behalf using the VIN+AB as the PO (i.e.VX12345AB). **Please ensure these air bag modules are used on the VIN specified in the PO only.**

We will provide an update when the next batch of customer letters are mailed.

Thank you,
Parts Logistics

Attachments: No Attachments No Attachments

Recipients: BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All
BMW Passenger Cars, All Offerings, All Regions, All Areas, Parts, All

