

**Subarunet Announcement**



**To: All Subaru Retailers**  
**From: Subaru of America, Inc.**  
**Date: September 14, 2016**

**UPDATE: WQR-53 Front Passenger Air Bag Inflator Owner Notification (2005 MY Legacy and Outback models)**

As previously announced, our parts supply for affected 2005-2009 model year Legacy and Outback vehicles has improved and we are continuing the second owner notification process. The second notification process is being handled in phases, based on the age of the inflator in the vehicle (oldest first).

On September 15, 2016, the next phase of these owner notification letters will be mailed to approximately 90,000 owners of affected 2005 model year Legacy and Outback vehicles that have not yet been repaired. Affected VIN lists will be distributed to each Zone Office prior to owner notification.

Make sure you review the latest revision of the WQR-53R Product Campaign Bulletin as found on STIS for the installation instructions and detailed parts information.

Thank you.