



We are concerned about your safety.

After several attempts to contact you, our records show that this issue with your vehicle is not resolved.

Your 2001 Honda Accord requires a safety repair.

Honda has decided that a defect which relates to motor vehicle safety exists in certain vehicles. In some vehicles, the driver side front airbag inflator could produce excessive internal pressure leading to a rupture upon deployment. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material and possibly hit you or others in the vehicle. Past ruptures like this have killed or injured vehicle drivers. Due to the severity of this defect, please call us immediately. Do not delay in contacting us. Alternative transportation is available pending repair.

It is extremely important to take steps now to repair your vehicle.

Any authorized Honda dealer can replace the front driver inflator at no charge to you.

Resolve this safety issue with one hassle-free phone call

We're waiting to hear from you:

CALL 1-844-758-9245 TODAY

Monday through Friday, 7 a.m. to 6 p.m. CST. We will schedule an appointment at your convenience to have this Safety Recall Performed at no charge.



For your convenience we have provided the last nine digits of your VIN below. Please refer to this number when scheduling your free appointment to verify your identity and vehicle.

Thank You,
Honda Recall Resolution Team

YOUR VEHICLE INFORMATION

2001 HONDA ACCORD
VIN XXXXXXXXXX

DEALERSHIP INSTRUCTIONS:
Please reference Campaign [CID].