



TMS Toyota Customer Services
Product Quality and Service Support, Quality Compliance
Published October 25, 2016
Approved By: Tom Trisdale

Toyota Motor Sales, USA, Inc.
19001 South Western Avenue
Torrance, CA 90501
(310) 468-4000

To: All Toyota Dealer
From: Product Support Division

****UPDATED****

****Dealer Letters and Technical Instructions Now Available on TIS****

Safety (Noncompliance) Recall G03 – *Remedy Notice*
Certain 2016 Model Year Highlander
Brake Fluid Reservoir Sensor Connector

- Labor Op Codes have been added for claim submission.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.