



This report, updated monthly, is designed to provide you with a summary of active NHTSA Defect Investigations. The investigations listed below are grouped according to type of investigation ([Preliminary Evaluation](#), [Engineering Analysis](#), [Recall Query](#), and [Defect/Recall Petition](#)) and identify the products under investigation, the alleged problem, and the investigation status. For up-to-date details on specific investigations, you can enter its Action # in the Quick Search box at: <http://www-odi.nhtsa.dot.gov/cars/problems/defect/defectsearch.cfm>

If you're having any safety problem with your vehicle, whether or not identified on the list below, please [Contact Us](#) today!

March 2012

MONTHLY DEFECT INVESTIGATION REPORT ENGINEERING ANALYSIS

Action#	MMY	Subject	Date Opened	Date Closed
EA09-005	2003-2005 INFINITI Q45 AND 2003-2004 INFINITI M45	SIDE AIR BAG NON-DEPLOYMENT	01-APR-2009	
EA09-013	MY 2002 - 2005 FORD EXPLORER / MERCURY MOUNTAINEER	VEHICLE ROLLAWAY ALLEGATIONS	18-AUG-2009	
EA10-003	1997-2008 E350/450 Ford Cab/Chassis	HVAC Switch Failures	13-APR-2010	05-MAR-2012
EA10-005	All 2008 and 2009 models with a Center Front Adjuster	Harness slippage	02-JUL-2010	
EA11-001	1999-2003 GM C/K pickup trucks and SUVs in Salt Belt states	Brake line corrosion failure	05-JAN-2011	
EA11-003	2009-2010 Volkswagen/Audi JETTA/Golf/A3 TDI Clean Diesel	High-Pressure Fuel Pump Failure (HPFP)	07-FEB-2011	
EA11-004	2006 Honda CR-V	Driver's Master Power Window Switch	11-APR-2011	
EA11-005	2004-2005 Mini Cooper	Loss of Power Steering Assist	04-MAY-2011	
EA11-007	MY 2008, 2009, 2010 DoubleTree (DRV) Recreational Vehicles	Wheel Separations (Broken Studs)	27-MAY-2011	
EA11-008	2006-2008 Pierce Contender EV	Engine RPM's surging during pumping mode	27-JUN-2011	
EA11-010	Model Year (MY) 2005 Chrysler Minivans	Loss of Headlight Illumination	06-SEP-2011	
EA11-011	2007 Sterling L-liner	Haldex Spring Brake Failures	09-SEP-2011	
EA11-012	Model Year 2002 through 2004 Honda CR-V	Low Beam Headlights Stop Working	12-SEP-2011	
EA11-013	MY 2004 - 2005 Jeep Liberty	Rear Suspension Control Arm Failure	15-SEP-2011	14-MAR-2012
EA11-014	2004-07 Saturn ION	Electric Power Steering Failure	29-SEP-2011	
EA11-015	MY 2007-2008 Saturn Aura	Transmission Cable Failure	10-NOV-2011	
EA12-001	2002-2003 Jeep Liberty	Inadvertent Air Bag Deployment	23-JAN-2012	

MONTHLY DEFECT INVESTIGATION REPORT PRELIMINARY EVALUATIONS

Action#	MMY	Subject	Date Opened	Date Closed
PE10-019	2010 Ford Fusion and Mercury Milan	Accelerator pedal entrapment.	28-MAY-2010	
PE10-031	1993-2004 Jeep Grand Cherokee	Crash Related Fuel Tank Fires	23-AUG-2010	
PE10-048	2006 Model Year Winnebago Itasca	Hitch Fracture	07-DEC-2010	
PE11-018	MY 2005 through 2007 Ford Freestyle	Throttle Control Malfunction	11-MAY-2011	
PE11-020	2007 - 2008 Nissan Altima	Brake Master Cylinder Internal Leak	23-MAY-2011	14-MAR-2012
PE11-025	MY 2002 through MY 2008 BMW 7 Series	Vehicle Rollaway Allegations	05-AUG-2011	
PE11-026	2008 Mazda CX-9	Brake master cylinder leak	09-AUG-2011	
PE11-033	MY 2004-2005 Ford Freestar & Mercury Monterey	Service Jack Failure	13-SEP-2011	
PE11-036	2007-2008 Mini Cooper S	Engine compartment fire	11-OCT-2011	
PE11-038	MY 2003-2004 Infiniti M45	Fuel level gauge system failure	14-DEC-2011	22-MAR-2012
PE11-039	2004 Ford Freestar and Mercury Monterey (salt-belt states)	Corrosion of the Third-Row Seat Mounting	21-DEC-2011	
PE11-040	2003 Chevrolet Express	Corrosion of the Fuel Filler Pipe	14-DEC-2011	
PE11-041	2011 Medtec R152 Type 1 Ambulance	Collapse of Squad Seat Base	20-JAN-2012	
PE12-001	2003-2006 E55 AMG Sedan and Wagon	Fuel System (Tank/Sender) Leakage	23-JAN-2012	
PE12-002	2007 Toyota RAV4 and Camry	Driver Door Fire	06-FEB-2012	
PE12-003	2006-2007 Chevrolet Trailblazers	Driver's Master Power Window Switch	09-FEB-2012	
PE12-004	2006- 2007 MY Tiffin equipped with Bosch ZOHT brakes	Diminished brake performance	17-FEB-2012	
PE12-005	MY 2005 and 2006 Ford Taurus	Stuck throttle	07-MAR-2012	
PE12-006	Transit busses using 8.1 compressed natural gas (CNG) engine	Turbocharger Failure	14-MAR-2012	
PE12-007	1992-2012 MCI D Series Buses with Steerable Tag Axle	MCI Driveshaft Safety Loop Failures	21-MAR-2012	
PE12-008	2007 - 2010 International 3200 IM buses	Engine compartment fires	22-MAR-2012	
PE12-009	MY 2010 Jeep Wrangler	Engine Compartment Fire	28-MAR-2012	
PE12-010	MY 2011 Chevrolet Cruze	Engine compartment fire	28-MAR-2012	

**MONTHLY DEFECT INVESTIGATION REPORT
RECALL QUERY**

Action#	MMY	Subject	Date Opened	Date Closed
----------------	------------	----------------	--------------------	--------------------

**MONTHLY DEFECT INVESTIGATION REPORT
PETITIONS**

Action#	MMY	Subject	Date Opened	Date Closed
----------------	------------	----------------	--------------------	--------------------

DP09-006	2005 - 07 MODEL YEAR BLUE BIRD WANDERLODGE M450 MOTOR HOME	ALLEGED INADEQUATE CAMPAIGN REMEDY	30-NOV-2009	
DP12-001	1998-2009 K1200LT	M/C final drive ball bearing failure	20-JAN-2012	

PRELIMINARY EVALUATION (PE)

Initial phase of a NHTSA investigation, a PE is prompted after a review of consumer complaints and/or manufacturer service bulletins suggest a safety defect may exist. The results of a PE determine whether the investigation will be upgraded to an Engineering Analysis or closed. Most PEs are resolved within four months.

ENGINEERING ANALYSIS (EA)

Second and final phase of a NHTSA investigation, an EA is undertaken if data from a PE indicate further examination of a potential safety defect is warranted. The results of an EA determine whether a safety recall should be initiated or the investigation should be closed. Most EAs are resolved within one year.

RECALL QUERY (RQ)

NHTSA monitors recalls to ensure that the scope, completion rate, and remedy are adequate. If recall adequacy comes into question, an RQ is opened to determine if the scope of the recall should be expanded or an adjustment in existing remedies is required.

DEFECT OR RECALL PETITION (DP OR RP)

NHTSA may be petitioned to investigate an alleged safety defect or whether a manufacturer has successfully carried out the requirements of a recall. If the petition is granted, NHTSA opens an appropriate investigation. If the petition is denied, the reasons for denial are published in the Federal Register.

If you have a safety concern or want to learn more...

4 WAYS TO CONTACT US

VISIT:

- www.safercar.gov

CALL:

- 1-888-327-4236

FAX:

- 202-493-2833 (Download complaint form , fill out and fax).

WRITE:

- National Highway Traffic Safety Administration
Office of Defects Investigations/CRD NVS-216
1200 New Jersey Ave SE
Washington, DC 20590