



13V-065  
(2 pages)

PO Box 2000 Goshen, IN 46527

February 26, 2013

**VIA E-MAIL  
RECEIPT CONFIRMATION REQUESTED**

Ms. Nancy Lewis  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
Attn: Recall Management Division (NVS-215)  
1200 New Jersey Ave. S.E.  
Washington, DC 20590

Re: Keystone RV Company  
Defect and Non-Compliance Report

Dear Ms. Lewis:

Keystone RV Company (“Keystone”) has decided that a defect which relates to motor vehicle safety exists in the recreational vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

- A. Recall Population and Vehicle Identification. The recall population includes the following product brands manufactured by Keystone.

<u>Product Brand</u>	<u>Number of Vehicles</u>
2013 Montana Fifth Wheels Production Dates: 1/16/2013 – 2/18/2013 VIN Range: 4YDF39024D4701739 - 4YDF37229D4702032	294
2013 Fuzion Fifth Wheels Production Dates: 1/22/2013 – 2/18/2013 VIN Range: 4YDF39028DF811312 - 4YDF31021DF811489	144
The total number of vehicles subject to this recall campaign is:	438

- B. Description of Defect. It has been decided Progressive Dynamics, Inc. PD4590 power converters manufactured between January 14, 2013, and February 8, 2013 with serial number prefix A13014 through A13039 and installed in Keystone vehicles indicated in the population above may have not have adequate gap (minimum .38”) between the two A/C stab rails under the main 50 amp A/C breakers. Less than 0.38” separation between the two A/C stab rails could result in arcing between the stab rails leading to an increased risk of fire, property damage and/or personal injury.

Manufacturer: Progressive Dynamics, Inc. 507 Industrial Road Marshall, Michigan 49068 Contact: Ralph McGee, President

- C. Basis for Determining that a Defect Exists. February 21, 2013 Keystone was notified by Progressive Dynamics of the defect. All Keystone vehicles manufactured with the Power Centers identified by Progressive Dynamics are included in the recall population.
- D. Remedying of Defect. The remedy is to inspect the stab rail for the proper gap and if incorrect the stab rails will be replaced with ones supplied by Keystone. The parts and service for this remedy will be supplied at no charge.
- E. Owner Notifications. Keystone will notify the owners of the recreational vehicles by letter beginning in March 2013 pending NHTSA approval. A final copy of the owner letter will also be provided to NHTSA, along with the dealer repair procedures.
- F. Quarterly Reporting Requirements. Keystone will be filing quarterly reports in connection with this recall campaign.
- G. Campaign Number. Keystone's identification code for this recall is 13-191.

If you need any additional information regarding this recall campaign, please feel free to contact me at 574-537-3925.

Sincerely,

Garett Carolus  
Keystone RV Company  
Technical Manager