



Kenworth Truck Company
P.O. Box 1000
Kirkland, WA 98083-1000

A Division of PACCAR

April 15, 2013

Subject: Safety Recall 13KWE – T270-T370 Seat Belt Anchor Reinforcement
NHTSA Recall # 13V-082
Vin No.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect which relates to motor vehicle safety exists in certain Kenworth model T270 and T370 vehicles manufactured between January 31, 2013 and February 4, 2013. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

On certain T270 and T370 models as identified above, the floor pan reinforcement bracket for the outboard seat belt floor attachment on the driver's seat was positioned incorrectly during assembly. This reinforcement is employed to secure the seat belt anchor to the floor of the cab. Incorrect positioning of the reinforcement may result in a failure of the seat belt anchor mounting, which could result in personal injury or death in the event of a crash.

The problem is...	Driver's seat belt anchor mounting could fail
What your dealer will do...	Relocate the seat belt anchor bracket reinforcement to the correct position
What you must do ...	Contact your dealer immediately to schedule an appointment

Kenworth has initiated a recall to relocate the seat belt anchor bracket reinforcement to the correct position. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take less than three hours, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Quality Services Manager