

May 14, 2013

Subject: Safety Recall 313-D – Seat Belt Buckle Cable
NHTSA # 13V-091
EXPIRATION DATE: NONE

VIN: 1NPBL49X3DD210705

ID- 1

USA CORE SUPPLY, INC.
99 BRALEY RD
EAST FREETOWN, MA 02717
US 210705

Dear Peterbilt Customer,

This notice is sent to you in accordance with the requirements of the National Highway Traffic Safety Administration.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain Peterbilt Model 567/579/587 vehicles manufactured between January 18, 2012 and February 25, 2013. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

The seat belt buckle anchoring cables may fray after being repeatedly bent during use. A frayed seatbelt cable could cause the belt system to fail in its function of restraining an occupant during a rapid deceleration or crash, resulting in possible injury or death.

<i>The problem is...</i>	Seat belt anchoring cables can fray and fail
<i>What your dealer will do...</i>	Replace the seat belt anchor cables
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to replace the seat belt anchor cables in your truck. Please contact your Peterbilt dealer immediately to schedule an appointment for this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at www.Peterbilt.com. This repair should take less than one hour, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.


If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Director Customer Service

May 14, 2013

Subject: Safety Recall 313-D – Seat Belt Buckle Cable
Transport Canada # 2013-077
EXPIRATION DATE: NONE

VIN: 1XPBD49X0ED219866

ID- 1153

DOYLES TRANSPORT LTD
BOX 572
PORT AUX BASQUE, NF A0M 1C0
Canada 219866

Dear Peterbilt Customer,

This notice is sent to you in accordance with the requirements of the National Highway Traffic Safety Administration.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain Peterbilt Model 567/579/587 vehicles manufactured between January 18, 2012 and February 25, 2013. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

The seat belt buckle anchoring cables may fray after being repeatedly bent during use. A frayed seatbelt cable could cause the belt system to fail in its function of restraining an occupant during a rapid deceleration or crash, resulting in possible injury or death.

The problem is...	Seat belt anchoring cables can fray and fail
What your dealer will do...	Replace the seat belt anchor cables
What you must do ...	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to replace the seat belt anchor cables in your truck. Please contact your Peterbilt dealer immediately to schedule an appointment for this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at www.Peterbilt.com. This repair should take less than one hour, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.


If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Director Customer Service