

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

CHILD SEATS:

None during November 2017.

EQUIPMENT:

Iowa Mold Tooling Co., Inc. (IMT) is recalling certain Dominator I Crane bodies sold for installation onto other chassis. These cranes have incorrect stabilizer arm locking pins that may not engage properly allowing the stabilizer arm to extend from the side of the vehicle while traveling. If the locking arm pin does not engage, the stabilizer arm may extend while the vehicle is in motion, increasing the risk of a crash. IMT will notify owners, and dealers will replace the incorrect pin with a correct length pin, free of charge. The recall is expected to begin in December 2017. Owners may contact IMT customer service at 1-800-247-5958. IMT's number for this recall is TB2017008.

17E-067

Prevost Cars, Inc. (Prevost) is recalling certain Kidde Plastic-Handle and Push Button 'Pindicator' Fire Extinguishers sold as accessory equipment for use in coaches. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Prevost will notify owners, and instruct them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 20, 2018. Owners may contact Prevost customer service at 1-866-870-2046, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information. Prevost's number for this recall is SR17-31.

17E-068

Volvo Trucks North America (Volvo) is recalling certain Kidde Plastic-Handle Fire Extinguishers sold as accessory equipment for use in Volvo trucks. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Volvo will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 19, 2018. Owners may contact Volvo customer service at 1-800-528-6586, or Kidde customer service toll-free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17E-069

Mack Trucks, Inc. (Mack) is recalling certain models of Kidde Plastic-Handle Fire Extinguishers sold as accessory equipment for use in Mack trucks. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher.

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Mack will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 19, 2018. Owners may contact Mack customer service at 1-610-709-2131 or Kidde customer service toll-free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17E-070

Prevost Cars, Inc. (Prevost) is recalling certain Recaro AM71, AM72 and AM80 commercial bus driver seats sold as aftermarket replacement parts. In the affected seats, the seat belt buckle may be stuck in the locked position, preventing the seat belt tongue from being able to be inserted and locked. If the seat belt cannot be latched, the bus may be operated without the seat belt being used, increasing the risk of injury in the event of a crash. Prevost will notify the purchasers, and dealers will inspect the driver seat belt buckles and replace them, if necessary, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Prevost customer service at 1-866-870-2046. Prevost's number for this recall is 17E035.

17E-071

TIRES:

None during November 2017.

VEHICLES:

Heartland Recreational Vehicles, LLC (Heartland) is recalling certain 2018 Prowler and Trail Runner recreational trailers. The wires for the electric brakes may get caught in the spring hangers during axle movement, possibly resulting in the wires being severed. A severed brake wire would reduce braking capability, increasing the risk of a crash. Heartland has notified owners, and dealers will clamp the wires out of the area of the spring hanger and shackle, free of charge. The recall began on November 14, 2017. Owners may contact Heartland customer service at 1-877-262-8032. Heartland's number for this recall is 99.01.36.

17V-689

Heartland Recreational Vehicles, LLC (Heartland) is recalling certain 2018 Pioneer recreational trailers. The liquid propane (LP) manifold block may be mounted too close to the center shackle, allowing the shackle to hit the LP hose fitting and cause a propane leak. A leaking LP system can increase the risk of a fire. Heartland has notified owners, and dealers will re-locate the manifold block further from the shackle area, free of charge. The recall began on November 14, 2017. Owners may contact Heartland customer service at 1-877-262-8032. Heartland's number for this recall is 99.01.37.

17V-690

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Nissan North America, Inc. (Nissan) is recalling 2017-2018 Infiniti QX30 vehicles. The driver's air bag may unexpectedly deploy due to insufficient grounding of the steering components if an electrostatic discharge occurs and the air bag clockspring is broken. If the driver air bag inadvertently deploys, it can increase the risk of injury and a crash. Nissan will notify owners, and dealers will add sufficient grounding to the steering components, free of charge. Interim notices informing owners of the safety risk are expected to be mailed December 2017. Owners will receive a second notice when remedy parts become available in Spring 2018. Owners may contact Infiniti customer service at 1-800-622-6200, option 7.

17V-691

Thor Motor Coach (TMC) is recalling certain 2018 Ace, Axis, Hurricane, Windsport, and Vegas motorhomes. The wiring for the trailer lights may have been inserted into the wrong locations of the trailer lighting socket causing the trailer lights to not function properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." If the trailer lights do not function as intended, it can increase the risk of a crash. Thor has notified owners and dealers will re-wire a new connector, free of charge. The recall began on November 21, 2017. Owners may contact TMC customer service at 1-877-500-1020. TMC's number for this recall is RC000148.

17V-692

REV Recreation Group (REV) is recalling certain 2017-2018 Fleetwood Jamboree and Holiday Rambler Vesta motorhomes. The hydraulic leveling system lines may not be properly secured allowing them to contact the axle or the chassis drive train components, possibly resulting in a hydraulic fluid leak. A leaking hydraulic fluid line can increase the risk of a fire or a crash. REV will notify owners, and dealers will secure the hydraulic lines with insulated clamps as necessary, replacing any damaged hydraulic lines, free of charge. The recall is expected to begin December 29, 2017. Owners may contact REV customer service at 1-800-509-3417. REV's number for this recall is 171102REV.

17V-693

Van-Con, Inc. (Van-Con) is recalling certain 2007-2017 Dual Rear Wheel school buses built on Chevrolet 3500 Express chassis. The seat barrier behind the driver seat may be pinned to the bulkhead preventing it from deforming in the event of an impact. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 222, "School Bus Passenger Seating and Crash Protection." If the barrier is too rigid to absorb an impact, the occupants will have an increased risk of injury. Van-Con will notify owners and will reposition the barrier as necessary, free of charge. The recall is expected to begin December 29, 2017. Owners may contact Van-Con customer service at 1-732-356-8484.

17V-694

Entegra Coach (Entegra) is recalling certain 2016-2018 Aspire, Anthem, Cornerstone, and Insignia motorhomes. The vehicles have lights that do not include reflectors and the vehicle does not have separate reflectors. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." Without the required reflectors, the motorhome may be less visible to other drivers, increasing the risk of a crash. Entegra will notify owners, and dealers will install compliant reflectors, free of charge. The recall is expected to begin December 2017. Owners

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

may contact Entegra customer service at 1-800-945-4787. Entegra's number for this recall is 9903363.

17V-695

Jayco, Inc. (Jayco) is recalling certain 2016-2018 Jay Flight SLX recreational trailers equipped with a 35 amp power converter. The electrical circuit from the battery does not have overcurrent protection such as a fuse or circuit breaker. In the event of an electrical short, the unprotected circuit increases the risk of a fire. Jayco will notify owners, and dealers will install a fuse harness assembly with a circuit breaker for overcurrent protection, free of charge. The recall is expected to begin December 2017. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is 9901362.

17V-696

Highland Ridge RV (Highland Ridge) is recalling certain 2018 Light recreational trailers, models 312BHTS and 275RLS. The safety chains on these vehicles may be rated for a Gross Vehicle Weight Rating (GVWR) of 7,600 lbs, however the trailer has a GVWR of 11,700 lbs. The lower rated safety chains may fail if the trailer detaches from the tow vehicle, increasing the risk of a crash. Highland Ridge will notify owners, and dealers will replace the 7,600 lb chains with 11,700 lb chains, free of charge. The recall began on December 4, 2017. Owners may contact Highland Ridge customer service at 1-260-768-7771. Highland Ridge's number for this recall is 9904364.

17V-697

Phoenix Motorcars (Phoenix) is recalling certain 2015 Zeus 300, and 2015-2017 Zeus 305 shuttle vans built on a Ford E-350 chassis. When the vehicle is fully loaded, it may exceed the Gross Axle Weight Rating (GAWR) and the Gross Vehicle Weight Rating (GVWR). As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 119, "New Pneumatic Tires-Other Than Passenger Cars," and number 120, "Wheels and Rims-Other Than Passenger Cars." If the vehicle is loaded to its maximum passenger capacity, the rear tires may fail, increasing the risk of a crash. Phoenix will notify owners, and dealers will inspect and replace all of the vehicle wheels and tires with ones of a higher load rating, free of charge. The recall is expected to begin January 3, 2018. Owners may contact Phoenix customer service at 1-909-987-0815.

17V-698

Forest River, Inc. (Forest River) is recalling certain 2018 Puma recreational trailers. The Federal Placards indicate incorrect tire load range and tire pressure (PSI) information. The placard states a tire size of ST205/75R15/D requiring 50PSI, however the installed tires are size ST205/75R15/C, requiring 65PSI. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims," and they also fail to comply with the requirements of 49 CFR Part 567, "Certification." The incorrect tire information can cause the operator to over-inflate the tires, which can cause premature tire failure, increasing the risk of a crash. Forest River will notify owners, and dealers will install a corrected Federal Placard, free of charge. The recall began on December 4, 2017. Owners may contact Forest River Customer Service at 1-574-642-0588. Forest River's number for this recall is 425-0560.

17V-699

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Triumph Motorcycles America, LTD (Triumph) is recalling certain 2016-2017 Speed Triple R and Speed Triple S motorcycles. A wire for the charging system may rub against a bracket for the ABS modulator, potentially resulting in an electrical short. An electrical short could cause the engine to stall, increasing the risk of a crash. Triumph will notify owners, and dealers will replace the affected wire, rerouting it to avoid contact with the bracket, free of charge. The recall began on December 14, 2017. Owners may contact Triumph customer service at 1-678-854-2010. Triumph's number for this recall is SB552.

17V-700

Subaru of America, Inc. (Subaru) is recalling certain 2018 Crosstrek vehicles. These vehicles may be equipped with an incorrect floor mat retention bracket, allowing the floor mat to move out of position and interfere with the accelerator or brake pedal operation. If the floor mat moves out of position and interferes with the accelerator or brake pedal operation, it can increase the risk of a crash. Subaru has notified owners, and dealers will inspect the floor mat retention bracket and replace it if necessary, free of charge. The recall began November 14, 2017. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for this recall is WTR-77.

17V-701

Crysteel Manufacturing Inc. (Crysteel) is recalling certain 2017 dump body vehicles built on Isuzu NRR-Series chassis. The driveshafts on these vehicles may detach from the rear universal joint. If the driveshaft detaches from the rear universal joint, the vehicle will lose propulsion, increasing the risk of a crash. Crysteel will notify owners, and Isuzu dealers will install a repair kit, free of charge. The recall began on December 6, 2017. Owners may contact Crysteel customer service at 1-800-533-0494.

17V-702

Kawasaki Motors Corp., U.S.A. (KMC) is recalling certain 2017-2018 ZR900AH, ZR900BH and ZR900BJ motorcycles. The rear shock absorber tie-rod frame mount holes can become elongated if the rear shock absorber bottoms out, affecting the operation of the shock absorber. If the rear shock absorber does not function properly, it can increase the risk of a crash. KMC will notify owners, and dealers will inspect the tie-rod mounting hole and replace the bracket or frame depending on the extent of the elongation of the tie-rod mounting hole, free of charge. The recall began on December 4, 2017. Owners may contact KMC customer service at 1-866-802-9381. KMC's number for this recall is MC17-04.

17V-703

Crestline Coach Ltd. (Crestline) is recalling certain 2016-2017 Icon 2.0 ambulances, equipped with 1000W inverters, model MMS 1012. If the vehicle is operated with the inverter disconnected from the conversion batteries, the inverter may overheat. If the inverter overheats, it can increase the risk of a fire. Crestline will notify owners and dealers will modify the wiring such that the inverter's DC output remains connected to the conversion batteries during all modes of operation, free of charge. The recall is expected to begin in December 2017. Owners may contact Crestline customer service at 1-306-934-8844.

17V-704

PACCAR Incorporated (PACCAR) is recalling certain 2017 Peterbilt 320 vehicles, equipped with Meritor disc brakes. The park brake chamber on these vehicles may be too small, which can cause the vehicle to move

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

unexpectedly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 121, "Air Brake Systems." A vehicle with an undersized parking brake could result in the vehicle moving unexpectedly, increasing the risk of a crash or injury to anyone in the path of the vehicle. PACCAR will notify owners, and dealers will replace the rear axle park brake chambers, free of charge. The recall is expected to begin December 31, 2017. Owners may contact Peterbilt customer service at 1-940-591-4000. PACCAR's number for this recall is 1117E.

17V-705

Honda (American Honda Motor Co.) is recalling certain 2017 Honda Civic Sedan and Coupe vehicles. The right halfshaft may have been improperly heat treated, reducing its strength. The improper heat treatment can result in the halfshaft breaking, preventing the engine from moving the vehicle, and can allow a possible roll away situation if the parking brake is not engaged. This can increase the risk of a crash. Honda will notify owners, and dealers will inspect the halfshaft's serial number, replacing it as necessary and aligning the front wheels, free of charge. The recall began December 8, 2017. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is K0E.

17V-706

Forest River, Inc. (Forest River) is recalling certain 2017-2018 Dynamax Isata vehicles, models ISC36DSD, ISC35DBD, ISC36DSD4X4, built on RAM chassis equipped with Cummins 6.7L Turbo Diesel engines that have Concentric-brand water pumps without a vent hole. These water pumps may leak coolant. The leaking water pump can increase the risk of an engine compartment fire. Forest River will notify owners and Chrysler/RAM dealers will replace the water pumps, free of charge. The recall began on December 4, 2017. Owners may contact Forest River customer service at 1-574-262-3474 extension 212, or Chrysler customer service at 1-800-853-1403. Forest River's number for this recall is 55-0564.

17V-707

Forest River, Inc. (Forest River) is recalling certain 2017-2018 XLR Toyhauler, Vengeance and Wolf Pack recreational trailers equipped with an optional generator. The generator's exhaust pipe is mounted too close to the trailer's plastic underbelly. The generator's exhaust may melt the trailer's underbelly, increasing the risk of a fire. Forest River will notify owners, and dealers will inspect the routing of the exhaust pipe, lowering it away from the plastic underbelly, as necessary, free of charge. The recall began on December 4, 2017. Owners may contact Forest River customer service at 1-260-499-2100. Forest River's number for this recall is 73-0535.

17V-708

Altec Industries Inc. (Altec) is recalling certain 1992-2000 Aerial Cable Placer AP45 vehicles. The boom tips on these vehicles may crack and fail. If the boom tip fails, it can increase the risk of injury. Altec will notify owners, and dealers will inspect the boom tip, replacing any that are of an old design or have cracks, free of charge. The recall began on December 7, 2017. Owners may contact Altec customer service at 1-877-462-5832. Altec's number for this recall is CSN655.

17V-709

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Pleasant Valley Teardrop Trailers LLC (Pleasant Valley) is recalling certain 2017-2018 MyPod, T@G, T@B 320, T@B 400, Cirrus 820, and Cirrus 920 travel trailers equipped with Kidde Plastic-Handle Fire Extinguishers, model 210D. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or requiring excessive force to activate the extinguisher. Additionally, the nozzle may detach from the valve assembly with enough force that it could cause injury and render the product inoperable. In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Pleasant Valley will notify owners and direct them to contact Kidde directly to get a replacement fire extinguisher, free of charge. The recall is expected to begin December 29, 2017. Owners may contact Pleasant Valley customer service at 1-330-852-4811 or Walter Kidde customer service at 1-855-271-0773.

17V-710

Forest River, Inc. (Forest River) is recalling certain 2018 Prime Time Fury recreational trailers. The information on the Federal Placard may be incorrect, stating that the vehicle is equipped with ST235/80R16E tires and 16X6.0JJ rims, however, the vehicle is actually equipped with ST225/75R15E tires and 15X6.0JJ rims. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims," and 49 CFR Part 567, "Certification." The placards do not indicate the correct tire/rim combination which could lead to the installation of incorrect replacement tires, potentially increasing the risk of a crash. Forest River will notify owners, and dealers will install new corrected Federal Placards, free of charge. The recall is expected to begin January 10, 2018. Owners may contact Forest River customer service at 1-574-862-1025. Forest River's number for this recall is 48-0575.

17V-711

Chrysler (FCA US LLC) is recalling certain 2018 Ram ProMaster vehicles. An incorrect rivet may have been used to attach the front door impact sensor which can cause the sensor housing to fracture. A fractured sensor could affect the deployment of the standard supplemental side airbags during certain side impact crashes, increasing the risk of injury. Chrysler will notify owners, and dealers will replace both front door impact pressure sensors, securing them with the correct rivets, free of charge. The recall is expected to begin January 3, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T64.

17V-712

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016-2017 G550 4Matic, G63 AMG, and G65 AMG vehicles. A malfunction of the Electronic Stability Program (ESP), while Distronic Plus is engaged, may cause the engine to not reduce power, regardless of the vehicle's speed, driving situation or brake application. Increased braking effort and/or shifting to neutral would be needed to stop the vehicle, lengthening the distance needed to stop the vehicle and increasing the risk of a crash. MBUSA will notify owners, and dealers will reprogram the ESP control unit software, free of charge. The recall began on December 6, 2017. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2017110007.

17V-713

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2017 E300, S65 AMG Coupe, S550, S65 AMG Cabriolet, S550 Cabriolet, S550e, S65 AMG, and Mercedes-Maybach S600 vehicles. A transistor within the power steering control unit may overheat resulting in the power steering system being disabled. If the power

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

steering assist is unexpectedly disabled, it may increase the risk of a crash. MBUSA will notify owners, and dealers will inspect the steering rack, replace it as necessary, free of charge. The recall is expected to begin in January 2018. Owners may contact MBUSA customer service at 1-877-496-3691.

17V-714

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2017-2018 GLC300, GLC300 4Matic, and GLC43 AMG vehicles. The fixed panoramic sun roof frontal and side plastic panels may have insufficient bonding, allowing the panels to separate during vehicle operation. If the sun roof panels detach from the vehicle, it can increase the risk of a crash or injury for following traffic. MBUSA will notify owners, and dealers will inspect the bonding on the sun roof panels, correcting it as necessary, free of charge. The recall is expected to begin December 2017. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2017110009.

17V-715

Nissan North America, Inc. (Nissan) is recalling certain 2016 Nissan Rogue vehicles. The vehicles have front passenger seat frames that may be improperly welded. As such, these vehicles fail to meet performance requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 202a, "Head Restraints" and FMVSS 207, "Seating Systems." In the event of a crash, the improperly welded seat back frames may increase the risk of injury. Nissan will notify owners, and dealers will replace the front passenger seat back assembly, free of charge. The recall is expected to begin January 08, 2018. Owners may contact Nissan customer service at 1-800-647-7261.

17V-716

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2018 Toyota CH-R vehicles. The electronic parking brake (EPB) may not operate properly, possibly causing the parking brake not to disengage after it is applied or prevent it from being applied. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard FMVSS number 135, "Light Vehicle Brake Systems." If the EPB cannot be applied, there is an increased risk of a vehicle rollaway if the vehicle is parked on a hill without being placed into "Park." Toyota has notified owners, and dealers will update the programming of the skid control ECU as necessary, free of charge. The recall began on November 30, 2017. Owners may contact Toyota at 1-800-331-4331. Toyota's number for this recall is H0W.

17V-717

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2012-2015 Prius Plug-in Hybrid vehicles. The hybrid battery contains an Electric Vehicle (EV) fuse that may fracture after repeated high-load driving conditions such as climbing long hills. The failed fuse may cause the hybrid system to shut down resulting in the loss of power. Loss of power while driving at higher speeds can increase the risk of a crash. Toyota will notify owners, and dealers will replace the EV fuse, free of charge. The recall is expected to begin January 8, 2018. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is H0R.

17V-718

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

BMW of North America, LLC (BMW) is recalling certain 2018 230i, 230i xDrive, M240i, M240i xDrive, M2, and X3 xDrive 30i SAV vehicles. These vehicles may have an error in the software for the instrument panel, causing the display to not properly illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 101, "Control and Displays." If the display does not illuminate during start up or does not illuminate various control and warning symbols while driving, it can increase the risk of a crash. BMW will notify owners, and dealers will update the instrument cluster display software, free of charge. The recall is expected to begin January 8, 2018. Owners may contact BMW customer service at 1-800-525-7417.

17V-719

BMW of North America, LLC (BMW) is recalling certain 2014-2018 BMW i3 electric and hybrid electric vehicles. Unbelted, small adult, drivers may be at a higher risk of neck injury in the event of a frontal crash. These vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection." During a frontal impact, unbelted, small adult, drivers could be at a higher risk of neck injury. BMW will notify owners, and dealers will update the Driver air bag control unit software, free of charge. The recall is expected to begin January 8, 2018. Owners may contact BMW customer service at the dedicated i3 recall number 1-855-269-3361.

17V-720

Smeal Holding LLC (Smeal) is recalling certain 2013-2017 Aerial and Pumper Fire Apparatus vehicles, equipped with Hale pressure relief valves in the water pumps used for fire fighting. Rings securing the valves may corrode over time after exposure to water, causing the ring to fail and the pressure relief valve to open, reducing the water pressure available for fire fighting. A reduction in water pressure may hinder fire fighting efforts, increasing the risk of injury. Smeal will notify owners, and Hale service providers will install a remedy kit, free of charge. The recall began on December 11, 2017. Owners may contact Smeal customer service at 1-800-543-5008 or Hale customer service at 1-800-533-3569. Smeal's number for this recall is 17028.

17V-721

Spartan Motors USA (Spartan) is recalling 2014-2017 Spartan Gladiator and MetroStar emergency response vehicles equipped with Hale pressure relief valves in the water pumps used for fire fighting. Rings securing the valves may corrode over time after exposure to water, causing the ring to fail and the pressure relief valve to open, reducing the water pressure available for fire fighting. A reduction in water pressure may hinder fire fighting efforts, increasing the risk of injury. Spartan will notify owners and Hale service providers will install a remedy kit, free of charge. The recall began on December 11, 2017. Owners may contact Spartan customer service at 1-800-543-5008 or Hale customer service at 1-800-533-3569. Spartan's number for this recall is 17028.

17V-722

Newmar Corporation (Newmar) is recalling certain 2015-2018 London Aire motorhomes built on Daimler Trucks (DTNA) chassis. When the high beams are activated, only the high beam bulbs illuminate instead of both the high beam and low beam bulbs as intended. If both the high beam and low beam bulbs do not illuminate, the reduced light output can affect the driver's visibility, increasing the risk of a crash. Newmar will notify owners and

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

DTNA dealers will modify the vehicles so that both beams illuminate when high beams are turned on, free of charge. The recall is expected to begin January 16, 2018. Owners may contact Daimler Trucks North America at 1-800-547-0712 or Newmar customer service at 1-800-731-8300.

17V-723

Forest River, Inc. (Forest River) is recalling certain 2017-2018 Dynamax recreational vehicles, models ISC24FWM, ISC24RWM, ISC24FWMCD and ISC24CBM. If the vehicle is parked with the engine running, carbon monoxide may enter the passenger cabin through open windows or other openings in the floor. If carbon monoxide enters the passenger cabin, it can increase the risk of injury or death. Forest River will notify owners, and dealers will install stainless steel exhaust tips to lengthen the exhaust, free of charge. The recall began on December 14, 2017. Owners may contact Forest River customer service at 1-574-262-3474. Forest River's number for this recall is 55-0565.

17V-724

Honda (American Honda Motor Co.) is recalling certain 2011-2017 Honda Odyssey vehicles. The second row outboard seats can slide sideways to one of two positions. If a seat is placed between either of the two positions when attaching the seat to the vehicle floor, the seat will not latch properly to the seat striker, allowing the seat to tip forward unexpectedly during braking. If the seat tips forward during braking, it can increase the risk of injury. The remedy for this recall is still under development. Honda will notify owners of the safety risk in an interim notification and provide detailed instructions for installing/positioning the second row outer seats and confirming that they are securely latched. Once a final remedy is determined and the necessary parts are available, Honda will send a second letter to the owners to have them visit a dealer to have the condition remedied, free of charge. The interim notification is expected to begin December 28, 2017. Owners may contact American Honda Customer Support & Campaign Center at 1-888-234-2138. Honda's number for this recall is S0G.

17V-725

Isuzu Technical Center of America, Inc. (Isuzu) is recalling certain 2011-2017 Isuzu NPR, 2008 NPR HD and NPR-HD Gas, 2011-2018 NPR HD and NRR, 2015-2018 NPR XD, 2012-2018 NQR, 2012-2017 NPR Gas and NPR-HD Gas, 2016-2017 Chevrolet Low Cab Forward 3500 HD, 3500 and 4500 and 2017-2018 Chevrolet Low Cab Forward 4500 HD, 4500 XD, 5500 HD and 5500 XD vehicles, equipped with certain Walter Kidde Plastic-Handle Fire Extinguishers, models FC10 and FC110. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Isuzu will notify owners, instructing them to contact Kidde to get a replacement fire extinguisher, free of charge. The recall is expected to begin in December 2017. Owners may contact Isuzu customer service at 1-866-441-9638 or Walter Kidde customer service at 1-855-271-0773 or they may also visit www.kidde.com and click on "Product Safety Recall" to order replacement fire extinguishers free of charge. Isuzu's number for this recall is V1705. Note: This recall includes fire extinguishers provided as a remedy for previous Isuzu recall 15V778.

17V-726

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

BMW of North America, LLC (BMW) is recalling certain 2018 BMW X5 SAV, X5 M SAV, X6 SAV, and X6 M SAV vehicles. Bolts that secure the front suspension may not have been properly tightened. Loose bolts can affect the performance of the suspension, thereby increasing the risk of a crash. BMW will notify owners, and dealers will inspect and tighten the wishbone suspension bolts, free of charge. The recall is expected to begin January 8, 2018. Owners may contact BMW customer service at 1-800-525-7417.

17V-727

Newell Coach Corp. (Newell) is recalling certain 2017-2018 P50 coaches. These coaches have 100 amp self-resetting circuit breakers that may trip unexpectedly causing a loss of essential coach chassis systems such as ignition power, head lights, tail lights and wipers. If the circuit breaker trips there is an increased risk of a crash. Newell will notify owners and will replace the 100 amp breaker with a 120 amp breaker, free of charge. The recall is expected to begin December 2017. Owners may contact Newell customer service at 1-888-363-9355.

17V-728

Daimler Trucks North America LLC (DTNA) is recalling certain 2016-2017 Thomas Built Buses Saf-T-Liner C2, Saf-T-Liner EFX, Saf-T-Liner HDX, and Minotour SRW school buses, equipped with IMMI-brand 3-point lap and shoulder belts. Under load, the seat belt buckle mount rod can fracture. As such, these seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 210, "Seat Belt Assembly Anchorages." In the event of a crash, if the buckle mount rod fractures, the seat occupant may not be restrained, increasing their risk of injury. DTNA will notify owners, and dealers will replace the seat belt buckle rods, free of charge. DTNA issues owners an interim notification on December 11, 2017. The recall is expected to begin January 15, 2018. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-753.

17V-729

Daimler Trucks North America LLC (DTNA) is recalling certain 2018 Freightliner Cascadia trucks equipped with Detroit automatic transmissions. A shift lock bolt within the transmission can seize, preventing the transmission from being shifted out of gear range 7 through 12. If the transmission cannot be shifted out of gear range 7 through 12, the engine may stall, increasing the risk of a crash. DTNA will notify owners, and dealers will inspect the transmissions and replace the transmission shift bolt, as necessary, free of charge. The recall is expected to begin January 15, 2018. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-754.

17V-730

Chrysler (FCA US LLC) is recalling certain 2018 Jeep Compass vehicles. The passenger side air bag assembly may have inflator mounting nuts loose within the module assembly. In the event of a crash necessitating air bag deployment, unsecured inflator mounting nuts outside of the cushion assembly are potential projectiles that may strike the driver or other occupants resulting in serious injury or death. Chrysler will notify owners, and dealers will replace the passenger air bag module assembly, free of charge. Chrysler issued owners an interim notification on December 15, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T73.

17V-732

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Burch Tank and Truck (Burch) is recalling certain 2017 Cargo tank trailers, equipped with MPA/MTA suspensions and Meritor EX225 brakes. The brake caliper bolts on these axles may not be properly torqued which can allow the caliper to detach from the mounting flange. If the caliper bolts are improperly torqued and the caliper detaches from the mounting flange, a loss of braking ability would occur, increasing the risk of a crash. Burch has notified owners, and fleets will be reimbursed by Meritor to inspect the bolts, and replace any loose or missing ones. The recall began on October 3, 2017. Owners may contact Burch customer service at 1-800-882-7640 or the Meritor call center at 1-866-668-7221.

17V-733

REV Recreation Group (REV) is recalling certain 2009-2010 and 2012-2014 Holiday Rambler Ambassador, 2010 and 2013-2014 Endeavor, 2009-2010 Neptune, 2010 Scepter, and 2011 Trip diesel motorhomes, equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. REV will notify owners, and instruct them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 18, 2018. Owners may contact REV customer service at 1-800-509-3417, or Kidde customer service at 1-855-271-0773 or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-734

Burch Tank and Truck (Burch) is recalling certain 2017 Heil Cargo tank trailers, equipped with MPA/MTA suspensions and Meritor EX225 brakes. The brake caliper bolts on these axles may not be properly torqued which can allow the caliper to detach from the mounting flange. If the caliper bolts are improperly torqued and the caliper detaches from the mounting flange, a loss of braking ability would occur, increasing the risk of a crash. Burch has notified owners, and fleets will be reimbursed by Meritor to inspect the bolts, and replace any loose or missing ones. The recall began on October 3, 2017. Owners may contact Burch customer service at 1-800-882-7640 or the Meritor call center at 1-866-668-7221.

17V-735

Winnebago Industries, Inc. (Winnebago) is recalling certain 2017-2018 Grand Tour and Journey motorhomes. The battery cables and hydraulic lines on these vehicles may not be properly secured, allowing them to contact the driveshaft or exhaust system, potentially resulting in an electrical short or hydraulic fluid leak. An electrical short can increase the risk of a fire. A hydraulic fluid leak can result in a loss of braking ability, increasing the risk of a crash. Winnebago will notify owners, and dealers will inspect the battery cables and hydraulic lines, rerouting and securing them as necessary. Any damaged cables or lines will be replaced. These repairs will be performed free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Winnebago customer service at 1-641-585-3535.

17V-736

Prevost Cars, Inc. (Prevost) is recalling certain 2009-2018 H3-41, H3-45, H3-45 VIP, X3-45, X3-45 VIP,

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

and X3-45 VIP Entertainer vehicles, equipped with certain Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit:

<https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Prevest will notify owners, and instruct them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 20, 2018. Owners may contact Prevest customer service at 1-866-870-2046, or Kidde customer service toll free at 1-855-271-0773 or online at www.kidde.com and click on "Product Safety Recall" for more information. Prevest's number for this recall is SR17-31.

17V-737

Supreme Corporation (Supreme) is recalling certain 2017 Supreme Signature Van, Iner-City and Kold King vehicles. These vehicles may have been built without rear and/or side reflex reflectors. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." Missing reflective devices reduce the vehicle's visibility, increasing the risk of a crash. Supreme will notify owners and send them new reflex reflectors with mounting instructions, free of charge. The recall is expected to begin December 2017. Owners may contact Supreme customer service at 1-800-642-4889.

17V-738

E-One Incorporated (E-One) is recalling certain 2013-2017 E-One Cyclone II, Quest, Typhoon, 2016 Freightliner M2 112, 2013-2015 International 7400, 2014-2017 International 4400, Freightliner M2 106, 2016-2017 Kenworth T370, and 2015 Kenworth T800 vehicles equipped with Hale pressure relief valves in the water pumps used for fire fighting. Rings securing the valves may corrode over time after exposure to water, causing the ring to fail and the pressure relief valve to open, reducing the water pressure available for fire fighting. A reduction in water pressure may hinder fire fighting efforts, increasing the risk of injury. E-One will notify owners, and a certified dealer or technician will install a stainless steel retaining ring, free of charge. The recall is expected to begin January 8, 2018. Owners may contact E-One customer service at 1-352-861-3612.

17V-739

Chrysler (FCA US LLC) is recalling certain model year 2017-2018 Jeep Compass vehicles. The brightness of the backlighting for the Instrument Panel Cluster (IPC) cannot be adjusted. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 101, "Controls and Displays." An instrument cluster that is too bright, and cannot be dimmed, can reduce the driver's ability to see at night, increasing the risk of a crash. Chrysler will notify owners, and dealers will update IPC software, as necessary, free of charge. The recall began December 8, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T70.

17V-740

Chrysler (FCA US LLC) is recalling certain 2014 Dodge Challenger, Charger, Durango, Chrysler 300, and Jeep

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Grand Cherokee vehicles equipped with a 3.6L engine and a 160 amp alternator. In the affected vehicles, the alternator may suddenly fail. If the alternator fails, the vehicle may stall without warning, increasing the risk of a crash. Chrysler will notify owners, and dealers will replace the alternator, free of charge. The recall began December 15, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T75.

17V-741

Daimler Vans USA, LLC (DVUSA) is recalling certain 2017 Mercedes-Benz and Freightliner Sprinter 2500 and 3500 vans. The spare tire holder under the vehicle may not be properly secured. If the spare tire holder is not properly secured, the spare tire may separate from the vehicle and become a road hazard, increasing the risk of a crash. DVUSA will notify owners and dealers will lift the spare tire holder completely and tighten the securing screws as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact DVUSA custom service at 1-854-888-3214.

17V-742

Grand Design RV, LLC (Grand Design) is recalling certain 2018 Reflection travel trailers, model 297RSTS. These vehicles may have insufficient clearance between the tire and the ram that moves the slide out room. The tire can contact the ram for the slide out room while the trailer is being towed, causing tire damage or a possible tire blowout. Tire failure can increase the risk of a crash. Grand Design will notify owners, and dealers will install a lift kit at each of the axle hangers, giving two additional inches of clearance. Tires that show evidence of damage will be replaced. These repairs will be performed free of charge. The recall began on December 14, 2017. Owners may contact Grand Design customer service at 1-574-825-9679. Grand Design's number for this recall is 910011.

17V-743

Mazda North American Operations (Mazda) is recalling certain 2017 CX-5 vehicles equipped with an accessory trailer hitch wiring harness. This harness may be routed such that there is insufficient clearance between the harness and the exhaust muffler, allowing the wiring harness to contact the muffler. Contact with the muffler may damage the trailer wiring harness, potentially resulting in the trailer lighting being inoperative, thereby increasing the risk of a crash. Mazda will notify owners, and dealers will reroute the trailer hitch harness away from the muffler, replacing the harness if it is damaged, free of charge. The recall is expected to begin January 20, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1617K.

17V-744

Mazda North American Operations (Mazda) is recalling certain 2018 Mazda3 vehicles, equipped with an incorrect exhaust valve spring. The incorrect exhaust valve spring may fail while driving, potentially causing an engine stall. An engine stall can increase the risk of a crash. Mazda will notify owners, and dealers will inspect the engines and replace any incorrect exhaust valve springs, free of charge. The recall is expected to begin January 20, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1717K.

17V-745

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

Jayco, Inc. (Jayco) is recalling various 2002-2016 recreational vehicles equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. A list of the affected trailer models is available at: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17V746-9524.pdf>. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Jayco will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Jayco customer service at 1-800-283-8267, or Kidde customer service toll-free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-746

Starcraft RV (Starcraft) is recalling certain 2009-2010 StarCraft, Centennial, Homestead, Travel Star, Travel Star EXP, Travel Star Sport, Autumn Ridge and Autumn Ridge SE recreational trailers, 2010 Rock Star, Lexion, Emblem and Homestead recreational trailers, 2013-2016 Comet recreational trailers, 2013-2015 AR-One and Launch recreational trailers, 2014-2016 Starflyer recreational trailers and 2016 Comet Hard Side recreational trailers. These trailers are equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers that may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Starcraft will notify owners, and instruct them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Starcraft customer service at 1-800-945-4787, or contact Kidde customer service toll-free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-747

Highland Ridge RV (Highland Ridge) is recalling certain 2010 Open Range, Residential and Rolling Thunder fifth wheels and 2010 Journeyer and Roamer recreational trailers. These vehicles are equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers that may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Highland Ridge will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Highland Ridge customer service at 1-260-768-7771, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

17V-748

KZRV, L.P. (KZRV) is recalling various 2002-2018 recreational trailers equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. See a list of the affected trailer models at: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17V749-9547.pdf>. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. KZRV will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact KZRV customer service at 1-800-768-4016 extension 154 or 153, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-749

Heartland Recreational Vehicles, LLC (Heartland) is recalling certain 2010-2011 Elkridge, North Country, North Trail FW, 2011 Big Country, Bighorn, Caliber, Country Ridge, Cyclone, Edge, Focus, Graystone, Landmark, MPG, North Trail TT, Road Warrior, Sundance, Sundance TT, Sundance XLT FW, Sundance XLT TT, Trail Runner, 2018 Fuel TT, 2016-2018 Sundance XLT TT, and Torque TT recreational vehicles, equipped with certain Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Heartland will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Heartland customer service at 1-877-262-8032, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-750

Cruiser RV (Cruiser) is recalling certain 2016-2017 Boss, Full House and Fun Finder Signature, 2018 Embrace and Striker FW, 2013-2016 Enterra and View Finder Signature, 2006-2016 Fun Finder, 2007-2015 Fun Finder Xtra, 2015-2017 Fun Finder Xtreme Lite and Shadow Cruiser Ultra Lite, 2016-2018 MPG, 2013-2017 Radiance, 2017-2018 Radiance Ultra Lite, 2010-2016 Shadow Cruiser, 2015-2016 Shadow Cruiser LE, 2017 South Fork, 2014-2018 Striker, 2009-2016 View Finder Lite, 2006-2007 Liberty, 2007 Land Roamer, 2009-2012 View Finder Toy Hauler, and 2006-2013 Fun Finder X recreational vehicles, equipped with certain Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

models visit: <https://static.nhtsa.gov/odi/rcl/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Cruiser will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Cruiser customer service at 1-866-277-5630, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-751

Entegra Coach (Entegra) is recalling certain 2010-2011 Aspire, Anthem, and Cornerstone recreational vehicles, equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rcl/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Entegra will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Entegra customer service at 1-800-945-4787, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-752

DRV Suites (DRV) is recalling certain 2007-2018 Elite Suites, 2014-2018 Full House, 2003-2018 Mobile Suites, 2010-2018 Mobile Suite Estates, 2006-2012 Select Suite, 2013-2016 Tradition, and 2017 Travel Suites recreational vehicles, equipped with certain Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rcl/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. DRV will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact DRV customer service at 1-574-457-6472, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-753

Bison Coach, LLC (Bison) is recalling certain 2010 Stratus, Aluma Sport, Trail Express, and Trail Hand recreational trailers, equipped with certain Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rcl/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Bison will

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Bison customer service at 1-574-658-4161, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-754

Keystone RV Company (Keystone) is recalling various 2003-2018 Coachmen, Dutchmen, and Keystone recreational trailers equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. A list of the affected trailer models is available at: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17V755-5127.pdf>. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Keystone will notify owners and instruct them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Keystone customer service at 1-574-535-2100, or Kidde customer service toll-free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information. Keystone's number for this recall is 17-307.

17V-755

Forest River, Inc. (Forest River) is recalling certain 2003-2018 Forest River Berkshire, Charleston, Rockport, Cedar Creek, Cherokee, Riverstone, Salem, Sandpiper, Sierra, Vengeance, Wildcat, Wildwood, XLR Boost, Cargo Mate, Continental Cargo, motorhomes, recreational trailers, toyhaulers, cargo trailers and restroom trailers and 2009-2018 Coachmen Mirada, Pursuit, Concord, Leprechaun, Freeland, Orion and Prism motorhomes, 2009-2017 Coachmen Apex and Catalina recreational trailers, and 2013-2017 Shasta Oasis and Revere recreational trailers, equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rc1/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Forest River will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 18, 2018. Owners may contact Forest River customer service at 1-800-348-7440, or Kidde customer service toll free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information. Forest River's number for this recall is 51-0544.

17V-756

Gulf Stream Coach, Inc. (Gulf Stream) is recalling certain 2018 Gulf Stream Coach 19FMB Breeze and Geo recreational trailers. The information on the Federal label lists an incorrect number of axles on the trailer. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification." The information regarding the trailer's gross axle weight rating (GAWR) for the front axle, tire, rim size and recommended tire pressure are correct, but there is only one axle, not two. Gulf Stream will notify the affected owner and dealers,

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

and will send a corrected label, free of charge. The recall began on December 15, 2017. Owners may contact Gulf Stream customer service at 1-800-289-8787. Gulf Stream's number for this recall is 20171125.

17V-757

Thor Motor Coach (Thor) is recalling various 2003-2018 recreational vehicles, equipped with Kidde Plastic-Handle or Push Button 'Pindicator' Fire Extinguishers. See a list of the affected trailer models at: <https://static.nhtsa.gov/odi/rcr/2017/RMISC-17V758-5764.pdf>. These extinguishers may become clogged, preventing the extinguisher from discharging as expected or excessive force may be needed to activate the extinguisher. Additionally, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and also render the product inoperable. For a full list of the affected fire extinguisher models visit: <https://static.nhtsa.gov/odi/rcr/2017/RMISC-17E062-5427.pdf> In the event of a fire, if the fire extinguisher does not function properly, it can increase the risk of injury. Thor will notify owners, instructing them to contact Kidde for a replacement fire extinguisher, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Thor customer service at 1-877-500-1020, or Kidde customer service toll-free at 1-855-271-0773, or online at www.kidde.com and click on "Product Safety Recall" for more information.

17V-758

Daimler Trucks North America LLC (DTNA) is recalling certain 2018 Freightliner 108SD, 114SD, Cascadia, M2 Business Class vehicles, 2018 Western Star 4700, 4900 and 5700 vehicles, and 2018 Freightliner Custom Chassis (FCC) S2C 106 chassis and S2G Cab/Chassis vehicles. The brake caliper mounting bolts on these vehicles may not be properly tightened, potentially resulting in the caliper detaching. If the calipers detach, there would be reduced braking performance, increasing the risk of a crash. DTNA will notify owners, and dealers will inspect the bolts, replacing them as needed, free of charge. The recall is expected to begin January 25, 2018. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-758.

17V-759

Daimler Trucks North America LLC (DTNA) is recalling certain 2018-2019 Thomas Built Buses Saf-T-Liner C2 school buses. The brake caliper mounting bolts on these vehicles may not be properly tightened, potentially resulting in the caliper detaching. If the calipers detach, there would be reduced braking performance, increasing the risk of a crash. DTNA will notify owners, and dealers will inspect the mounting bolts, replacing them as needed, free of charge. The recall is expected to begin January 25, 2018. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-758.

17V-760

Daimler Trucks North America, LLC (DTNA) is recalling certain 2008-2018 Freightliner Cascadia, Western Star 4700, 4900, 5700, and 6900 trucks. After hard brake applications, the brake light pressure switch may not activate the brake lights with a light application of the brake pedal. If the brake lights fail to illuminate, there would not be a signal to other motorists that the vehicle is slowing, increasing the risk of a crash. DTNA will notify owners, and dealers will repair the vehicles, free of charge. The recall is expected to begin January 25, 2018. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-756.

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

17V-761

Zero Motorcycles Inc. (Zero) is recalling certain 2018 S ZF13.0, S ZF7.2, SR ZF14.4, DS ZF13.0, DSR ZF14.4, FX ZF7.2, and FXS ZF7.2 motorcycles. The information on the Vehicle Emission Control Information (VECI) Label may indicate the wrong model year. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification." If the affected 2018 motorcycles are ever subject to a recall, the owner may not realize the safety risk because of the misstated model year. Zero will notify owners, and dealers will replace the incorrect label with a corrected label, free of charge. The recall is expected to begin in December 2017. Owners may contact Zero customer service at 1-888-841-8085. Zero's number for this recall is SV-ZMC-017-380.

17V-762

Southeast Toyota Distributors, LLC (SET) is recalling certain 2015-2018 Toyota 4Runner vehicles equipped with an accessory Billet Grille Overlay installed by SET or provided by SET and installed by SET dealers. The U-nut that secures the overlay grille may fracture, allowing the Billet Grille Overlay to detach from the vehicle. If the Billet Grille Overlay detaches while driving, it can become a road hazard, increasing the risk of a crash. SET will notify owners, and dealers will replace the securing U-nuts with upgraded hardware, free of charge. The recall is expected to begin January 26, 2018. Owners may contact SET customer service at 1-866-405-4226. SET's number for this recall is SET17C.

17V-763

Bugatti is recalling certain 2017-2018 Chiron vehicles. The front seat recliner brackets may not be welded properly, which can cause the back of the seat to move unexpectedly, affecting the driver's seating position. If the driver's seating position changes unexpectedly, it could increase the risk of a crash. Bugatti will notify owners, and service centers will inspect the welds on the recliner brackets for both seats, replacing the seat assembly, as necessary, free of charge. The recall began on December 7, 2017. Owners may contact Bugatti customer service at 1-805-557-1050.

17V-764

Kovatch Mobile Equipment Corp. (KME) is recalling certain 2015 Predator SS Tanker and Commercial Pumper built on Freightliner chassis, 2015-2018 Predator SS Pumper and Commercial Pumper built on Navistar chassis, 2016 Predator Panther Aerial and Predator Aerial, 2015-2017 Predator Panther Pumper and 2018 Predator SS Aerial vehicles equipped with Hale pressure relief valves in the water pumps used for fire fighting. Rings securing the valves may corrode over time after exposure to water, causing the ring to fail and the pressure relief valve to open, reducing the water pressure available for fire fighting. A reduction in water pressure may hinder fire fighting efforts, increasing the risk of injury. KME will notify owners, and KME dealers will install a remedy kit, free of charge. The recall is expected to begin January 2, 2018. Owners may contact KME customer service at 1-800-235-3926 or Hale customer service at 1-800-533-3569.

17V-765

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Atlas vehicles. The fuel tank may

**SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING NOVEMBER 2017**

Published December 20, 2017

have been manufactured with insufficient wall thickness, potentially resulting in the tank leaking fuel. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 301, "Fuel System Integrity." A fuel leak in the presence of an ignition source can increase the risk of a fire. Volkswagen will notify owners, and dealers will replace the fuel tank, free of charge. The recall is expected to begin December 29, 2017. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 20AQ.

17V-766

Ford Motor Company (Ford) is recalling certain 2016 F-150 and Explorer vehicles. Loose power seat adjuster pivot bolts may cause the front seat cushions to detach and not properly restrain the seat occupant in the event of a crash. In the event of a crash, a seat occupant that is not properly restrained has an increased risk of injury. Ford will notify owners, and dealers will inspect the tightness of the power seat track upper pivot link bolt, either applying threadlocker or replacing the lift link and hardware, free of charge. Interim letters are expected to go out January 15, 2018. Owners will receive a second notice when the remedy becomes available. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S40.

17V-767

Ford Motor Company (Ford) is recalling certain 2017 F-53 stripped motorhome chassis and F-59 stripped commercial chassis, equipped with Antilock Brake Systems (ABS). The brake Hydraulic Electronic Control Units (HECU) on these vehicles may be missing valve block ball plugs, potentially causing a brake fluid leak or air ingestion during electronic brake distribution and/or ABS activation. A brake fluid leak or air ingestion can lengthen the distance needed to stop the vehicle, increasing the risk of a crash. Ford will notify owners, and dealers will inspect the HECU for missing valve block ball plugs, replacing the unit as necessary, free of charge. The recall is expected to begin January 22, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S41.

17V-768

Hyundai Motor Company (Hyundai) is recalling certain 2013-2014 Elantra sedan, coupe and GT vehicles. The brake pedal stopper pad can deteriorate allowing the brake light switch plunger to remain extended when the brake pedal is released. This will allow the brake lights to remain illuminated continuously. It can also allow the shift lever to be moved without depressing the brake pedal, or activate the engine management brake pedal override feature. If the brake light switch plunger does not retract as it should when the brake pedal is not being pressed, the brake lights may stay illuminated preventing accurate communication to following vehicles that the vehicle is slowing or stopping. Additionally, if the brake switch plunger is not retracted, then the transmission can be shifted out of PARK without depressing the brake pedal. Either condition increases the risk of a crash. Hyundai will notify owners, and dealers will replace the brake pedal stopper pad, free of charge. The recall is expected to begin February 8, 2018. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 170. This campaign expands recall 16V574.

17V-769