



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

400 Seventh Street, SW
Washington, DC 20590

FEB 27 2003

**INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF
DEFECT INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 03E-011 by the
National Highway Traffic Safety Administration

Part 573 Report Date: February 12, 2003

MANUFACTURER: Dayton Wire Wheel, Inc.

MANUFACTURER CONTACT: Mr. Charles Schroeder
President

FAX: 937-438-1215

SUBJECT: 32 aftermarket replacement American Wire Wheels, Models SuperspokesII (P/N M0163540S-184) and Superspoke (P/N M12121540S-200 & M32121540S-200). The steel spokes can pull out of the machined aluminum hub which will result in complete failure of the wheel.

This is an initial acknowledgment for this recall. A formal acknowledgment letter will be forthcoming shortly. After our review of your report and associated documents, we may have additional comments or concerns.

NOTIFICATION TO PURCHASERS

It is our understanding that all of the affect wheels have been captured at your distributors and that none of the wheels have been sold to consumers. Therefore, it is not necessary for your company to submit an owner notification letter in accordance with Part 577. However, we require that Dayton submit one quarterly status report for our file.

If you have any questions, please call:

Kelly Schuler, Safety Defect Analyst or George Person, Chief
at (202) 366-5227 or by FAX (202) 366-7882

Recall Management Division

kschuler@nhtsa.dot.gov

Faxed on 2/27/03

* * * COMMUNICATION RESULT REPORT (FEB.27.2003 1:12PM) * * *

TTI NHTSA/OFC DEFECTS INV

FILE MODE	OPTION	ADDRESS (GROUP)	RESULT	PAGE
088	MEMORY TX	919374381215	OK	P. 1/1

REASON FOR ERROR

E-1) HANG UP OR LINE FAIL
E-3) NO ANSWER

E-2) BUSY
E-4) NO FACSIMILE CONNECTION



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

400 Seventh Street, SW
Washington, DC 20590

FEB 27 2003

**INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF
DEFECT INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 03E-011 by the
National Highway Traffic Safety Administration

Part 573 Report Date: February 12, 2003

MANUFACTURER: Dayton Wire Wheel, Inc.

MANUFACTURER CONTACT: Mr. Charles Schroeder
President

FAX: 937-438-1215

SUBJECT: 32 aftermarket replacement American Wire Wheels Models S... ..