

# SAFETY RECALL ALERT



**To:** Mack Dealer Principals  
Mack Warranty Managers  
Mack Service Managers  
Mack Parts Managers  
**From:** Regulatory Affairs Department

**Bulletin:** SRA-M12-07  
**Date:** October 18, 2012  
**Replaces:** N/A  
**Action:** **YES**

**Subject:** Safety Recall, SC0366, Focal Mounted Retarder Control

---

On certain Mack GU, LEU, and MRU model vehicles manufactured from December 12, 2007 through May 8, 2008 with a certain focal mounted retarder control box, the focal mounted retarder's control box can lose ground, which can result in localized overheating and possibly lead to a vehicle fire.

There are approximately 260 vehicles affected, all USA.

#### Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

#### Release Schedule:

- Vehicle list is posted on the Trucks Dealer Portal
- Owner Notices are scheduled to be mailed on or before October 22, 2012
- There is only one customer involved and the customer is involved in developing the repair protocol.

#### Questions:

Contact the Regulatory Affairs Department at [ytna.regulatoryaffairs@volvo.com](mailto:ytna.regulatoryaffairs@volvo.com) if you have questions.