



Forest River, Inc.

55470 County Road 1, P.O. Box 3030, Elkhart, Indiana 46515-3030 • 574-389-4600 • Fax 574-296-7558

RECEIVED

By Recall Management Division at 9:48 am, Feb 01, 2013

February 1, 2013

Ms. Nancy Lewis
Associate Administrator of Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Ave. SE
Washington, D.C. 20590

Dear Ms. Lewis:

Subject: General Motors Chevrolet Express and GMC Savana 2013 chassis nonconformance to FMVSS Standard 114.

The following information is submitted to the requirements of 49 CFR 573.6 as it applies to a determination by Forest River, Inc. of a noncompliance involving certain 2013 model year (MY) Chevrolet Express and GMC Savana vehicles as reported to FR by the General Motors Company.

573.6 (c) (1): Chevrolet and GMC Brands of General Motors Company.

573.6(c) (2) (3) (4): This information is shown on the attached sheet obtained from General Motors Company.

573.6(c) (5): General Motors has decided that certain 2013 model year Chevrolet Express and GMC Savana vehicles fail to conform to Federal Motor Vehicle Safety Standard 114 for ignition key retention, these vehicles have a condition where the ignition key can be removed from the ignition when it is not in the OFF position. This could allow theft of the vehicle or unintended movement of the vehicle, resulting in a possible crash.

573.6(c) (7): Forest River was notified with a safety recall notice on or about January 20, 2013 by U.S. mail.

“The Two Forests of Forest River... Forming Relationships with Nature”

573.6(c) (8) General Motors will notify owners on behalf of Forest River, General Motors dealers are to replace the ignition lock cylinder and the two associated keys.

Sincerely

A handwritten signature in black ink, appearing to read "William G. Conway Jr.", written in a cursive style.

William G. Conway Jr.
Chief Corporate Engineer

573.6(c)(2),(3),(4)

**VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR
PLUS INCLUSIVE DATES OF MANUFACTURE**

| <u>MAKE</u> | <u>MODEL SERIES</u> | <u>MODEL YEAR</u> | <u>NUMBER INVOLVED</u> | <u>INCLUSIVE MANUFACTURING DATES (FROM) (TO)</u> | | <u>DESCRIPTIVE INFO. TO PROPERLY IDENT. VEH.</u> | <u>EST. NO. W/CONDITION</u> |
|-------------|---------------------|-------------------|------------------------|--|------------|--|-----------------------------|
| Chevrolet | G/H | 2013 | 971 | 11/01/2012 | 12/21/2012 | Express | * |
| GMC | G/H | 2013 | 9 | 11/14/2012 | 11/20/2012 | Savanna | " |
| | GM Total: | | 980 | | | | |

* All involved vehicles will be corrected as necessary.

573.6(c)(2)(iv): STRATTEC Security Corp.
3333 West Good Hope Rd.
Milwaukee, WI 53209
Main Line: 414-247-3333

The suspect parts were manufactured in Chihuahua, Mexico.

12332