

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: E8x, E9x Power Distribution Box Connection Recall
Date: Thursday, February 07, 2013 5:13:29 PM

Publish Date: February 07, 2013
From: Technical Service
Expiration Date: February 21, 2013

DCSnet Message 
Important

Subject: **E8x, E9x Power Distribution Box Connection Recall**

To: BMW Service Managers, BMW Service Advisors,

BMW is conducting a voluntary safety Recall on certain model year 2007-2012 1 Series, 3 Series and Z4 vehicles.

This Recall involves the power supply system. The connection between the positive battery cable and the front power distribution box could degrade over time. An amended repair cable, with an improved electrical contact, will be installed at the front power distribution box.

Special tools required for the repair will be auto-shipped to centers during the week of February 25. An initial supply of parts and the Service Information bulletin will be made available at that time.

Do not order any parts at this time. Relevant parts have been blocked from ordering. If a vehicle exhibits the symptoms referenced in SI B61 08 11, before the Recall has been released, submit a PuMA case with the Subject "Vehicle Electrical System Failure" for instructions.

The mailing of customer Recall letters will be staggered throughout the month of March.

Attached is a list of Questions and Answers which should address most inquiries customers may have. Please provide and discuss this information with your staff.

Sincerely,

Technical Service

Attachments:  [2013-E9x-E8x-PowerSupplySystem_QA_4 \[80f980ca\].pdf](#)  [2013-E9x-E8x-PowerSupplySystem_QA_4 \[80f980ca\].pdf](#)

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All