



Applies To: **2001–03 Civic** – Check the iN VIN status for eligibility
2002–03 CR-V – Check the iN VIN status for eligibility
2002–03 Odyssey – Check the iN VIN status for eligibility

April 11, 2013

Safety Recall: Front Passenger’s Airbag Inflator Can Be Over-Pressurized

(Complete repair procedures to be posted around Friday, April 19, 2013.)



CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.