

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: N20, N26 Vacuum Pump Oil Supply, Update 5
Date: Thursday, October 24, 2013 10:44:48 AM

Publish Date: October 24, 2013
From: Technical Service
Expiration Date: November 07, 2013

DCSnet Message 
Urgent

Subject: **N20, N26 Vacuum Pump Oil Supply, Update 5**

This DCS updates the version published 10/23/2013. The changes are to the warranty information in the attachment.

The intake camshaft inspection procedure can be found as an attachment to this DCS message. In addition to this procedure, a modified intake camshaft replacement procedure is also provided in the same document. Follow this modified procedure in conjunction with the ISTA/D repair instructions where noted. This procedure is to be used on in-stock vehicles held by the Vacuum Pump Oil Supply Delivery Stop. Affected vehicles can be identified in DCS Warranty Vehicle Inquiry with a Vehicle Comment.

Vehicles which pass the inspection procedure can be released for retail delivery. Parts supply remains limited, and the ordering procedure outlined in the DCS message dated 10/15/13 remains in effect.

Sincerely,
Technical Service

Attachments:  [N20 N26 CamCheck 10 24 2013\[8111a358\].pdf](#) 
[N20 N26 CamCheck 10 24 2013\[8111a358\].pdf](#)

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All
BMW Passenger Cars, All Offerings, All Regions, All Areas, Sales, New Vehicle Sales Manager
BMW Passenger Cars, All Offerings, All Regions, All Areas, Sales, General Sales Manager
BMW Passenger Cars, All Offerings, All Regions, All Areas, Parts, Parts and Service Director