



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 9, 2013

Ms. Lynn Beattie
Vice President
ATI Performance Products, Inc.
6747 Whitestone Road
Gwynn Oak, MD 21207

NVS-215KS
13E-063

Subject: Transmission May Not Have a Strong Park

Dear Ms. Beattie:

This letter serves to acknowledge ATI Performance Products, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
POWERGLIDE/200660SC/9999

Mfr's Report Date: November 1, 2013

NHTSA Campaign Number: 13E-063

Components:
EQUIPMENT
POWER TRAIN:AUTOMATIC TRANSMISSION

Potential Number of Units Affected: 52

Problem Description:

ATI Performance Products, Incorporated (ATI) is recalling certain Powerglide model 200660SC automatic transmissions used in 2013 COPO Chevrolet Camaros. The affected transmissions may have weak park pawl.

Consequence:

If the transmission has a weak pawl, the transmission may come out of park and the vehicle may roll away, increasing the risk of a crash.

Remedy:

ATI will notify owners, and dealers will inspect and replace the transmission and torque converter, as necessary, free of charge. The recall is expected to begin in December 2013.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received ATI's proposed owner notification letter and envelope and they are currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

On August 20, 2013, NHTSA announced new changes to the requirements governing safety recalls. Some of these requirements are already in effect. Please ensure your company will be in compliance with each requirement on, or before, its respective effective date. For a summary of the requirements and their effective dates please click on the "New!" link at <http://www.safercar.gov/Vehicle+Manufacturers>.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement