



Dear Valued Evenflo Retailer:

Please be advised that Evenflo Company, Inc. ("Evenflo") has decided, as of April 4, 2014, to recall select 2011-2014 toddler convertible car seats and harnessed booster seats, identified below by name and date of manufacture. In many instances, these products have already been sold through your inventory. Please note that none of these products currently being shipped or manufactured for you are subject to this recall.

***PLEASE
CONSULT THE
ATTACHED
EXHIBIT A FOR
THE IMPACTED
UPC/SKU LIST
FOR YOUR
STORE.**

Model Names*	Affected Dates of Manufacture*
Momentum 65, Momentum 65 LX and Momentum 65 DLX	3/4/2013 through 8/26/2013
Chase, Chase LX and Chase Select	6/12/2012 through 10/3/2013
Chase LX and Chase DLX	8/23/2011 through 3/3/2014
Maestro and Maestro Performance	8/22/2011 through 10/17/2013
Symphony 65, Symphony LX and Symphony DLX	10/2/2012 through 8/26/2013
Symphony 65, Symphony 65 E3, Symphony DLX and Snugli All-in-One	10/2/2012 through 8/26/2013
Titan 65 and SureRide DLX	6/20/2012 through 10/17/2013
Secure Kid LX, Secure Kid DLX, Secure Kid 100, Secure Kid 300, Secure Kid 400 and Snugli Booster	12/13/2011 through 3/3/2014

The date of manufacture is located on the white 4x3 bar code shipping label on the car seat or booster carton. The date is in year/month/day format. In the label below, 2014/02/24 means a manufacturing date of February 24, 2014; therefore, this seat would not be subject to recall, even though it is a model with a 346 prefix.



Sample date code

These select models of car seats and boosters use a harness crotch buckle which may become resistant to unlatching over time, due to exposure to various contaminants, like food and drinks. This condition may make it difficult to remove a child from the restraint, increasing the risk of injury in the event of an emergency situation where prompt exit of the vehicle is necessary. There is no such risk if the buckle is functioning normally. These car seats and boosters meet all requirements for crashworthiness under FMVSS 213.

Evenflo is providing at no charge to the consumers who have own affected car seats and boosters a remedy kit that includes a replacement buckle and instructions for installation. The remedy kit is available by contacting Evenflo at www.buckle.evenflo.com or 1-800-490-7591. We have asked consumers not to return these car seats and boosters to retailers.

Please note that it is a violation of federal law for a retailer to sell or deliver any affected product covered by this recall unless the product is remedied. Please contact your Evenflo sales representative with questions about this recall. In addition, we are enclosing a recall poster that we would like you to post in a prominent location for the next 120 days.

We anticipate that with our support efforts we can minimize the disruption this recall may cause and move forward with our growing partnership.